

CARBON FOOTPRINT

EMBODIED (A1-A5 + B1-B5 + C)
All sites

Embodied carbon is the sum of greenhouse gas emissions released during the following life-cycle stages: raw material extraction, transport to manufacturer, manufacturing, construction, use phase, maintenance, replacement, renovation, and end-of-life.

Please note that the figures given below are based on the information provided in the platform. Incorrect or missing information can lead to unrepresentative results for your deposits.


CARBON FOOTPRINT - all deposits



114 / 143 deposits considered
1,79 / 2,71 tons of deposits

Information is missing for 81 of the 114 deposits considered.

tons Co₂ eq.



CARBON FOOTPRINT

EMBODIED (A1-A5 + B1-B5 + C)

ALL CATEGORIES OF PRODUCTS

Category	Number of deposits considered	Weight (Tons)	Percentage of total weight	Carbon footprint Embodied carbon (Tons CO2 eq.)	Emission intensity (Tons CO2 eq. /Ton of products)
Total	114	1,79	100,0%	6,16	3,44
Indoor furniture, accessories & décor	30	0,656	36,6%	1,83	2,79
Floor coverings	17	0,454	25,3%	1,30	2,86
Opening protections	4	0,045	2,5%	0,882	19,7
Sanitary equipment	12	0,274	15,3%	0,725	2,65
Electrical installations – CFO/CFA networks	23	0,056	3,1%	0,531	9,55
Furniture and accessories	2	0,070	3,9%	0,208	2,97
Partitioning, wall lining & interior insulation	2	0,064	3,6%	0,173	2,70
Other construction products and materials	5	0,069	3,9%	0,157	2,27
Sanitary systems / networks	5	0,029	1,6%	0,156	5,40
Clothing	2	0,006	0,3%	0,075	13,5
Other	2	0,004	0,2%	0,052	14,5

CARBON FOOTPRINT

EMBODIED (A1-A5 + B1-B5 + C)

ALL CATEGORIES OF PRODUCTS

Category	Number of deposits considered	Weight (Tons)	Percentage of total weight	Carbon footprint Embodied carbon (Tons CO2 eq.)	Emission intensity (Tons CO2 eq./Ton of products)
Interior joinery	2	0,050	2,8%	0,045	0,893
Facade	5	0,006	0,4%	0,015	2,29
Interior wall coverings	2	0,008	0,5%	0,014	1,66
Exterior joinery	1	0,000	0,0%	0,001	3,18

CARBON FOOTPRINT

ISO 14044/EN 15978 METHODOLOGY

All sites

The EN 15978 standard calculates the carbon intensity of a building in kgCO₂eq per m² of living area/useful surface over 50 years. Based on the ISO 14044 and EN 15804/ISO 21930 standards, the EN 15978 calculation takes into account the carbon emissions of all the components of the site(s) selected, from the extraction of raw materials to the end-of-life of the products, including their manufacture, installation and maintenance. Please note that the results below depend on the product passports selected. Incorrect or missing information may lead to incorrect results.

ISO 14044/EN 15978 - all deposits


Living area : 60 sqm



114 / 143 deposits considered
1,79 / 2,71 tons of deposits

Information is missing for 107 of the 114 deposits considered.

kg Co₂ eq. / sqm



CARBON FOOTPRINT

ISO 14044/EN 15978 METHODOLOGY

ALL CATEGORIES OF PRODUCTS

Category	Number of deposits considered	Weight (Tons)	Percentage of total weight	Carbon footprint (kg CO2 eq. / sqm)	Emission intensity (Tons CO2 eq. /Ton of products)
Total	114	1,79	100,0%	1 546	Unknown
Indoor furniture, accessories & décor	30	0,656	36,6%	703	Unknown
Floor coverings	17	0,454	25,3%	158	Unknown
Opening protections	4	0,045	2,5%	150	Unknown
Electrical installations – CFO/CFA networks	23	0,056	3,1%	146	Unknown
Furniture and accessories	2	0,070	3,9%	141	Unknown
Sanitary equipment	12	0,274	15,3%	70,9	Unknown
Other construction products and materials	5	0,069	3,9%	50,7	Unknown
Interior joinery	2	0,050	2,8%	37,9	Unknown
Clothing	2	0,006	0,3%	25,6	Unknown
Other	2	0,004	0,2%	25,3	Unknown
Sanitary systems / networks	5	0,029	1,6%	23,9	Unknown

CARBON FOOTPRINT

ISO 14044/EN 15978 METHODOLOGY

ALL CATEGORIES OF PRODUCTS

Category	Number of deposits considered	Weight (Tons)	Percentage of total weight	Carbon footprint (kg CO2 eq. / sqm)	Emission intensity (Tons CO2 eq. /Ton of products)
Partitioning, wall lining & interior insulation	2	0,064	3,6%	10,2	Unknown
Facade	5	0,006	0,4%	1,75	Unknown
Interior wall coverings	2	0,008	0,5%	1,09	Unknown
Exterior joinery	1	0,000	0,0%	0,082	Unknown

CARBON FOOTPRINT

ERROR REPORT (56 errors, 403 warnings)

Here are listed the errors and warnings that were generated during the calculation of the report. They are generally linked to insufficient or imprecise filling of product passports.

⚠ - Warning: a data is missing - the concerned deposit has been taken into account but the result of the indicator for this deposit may be non representative or partial

⊗ - Error: an important data is missing - the concerned deposit could not be taken into account in the calculation of the indicator

In both cases, we recommend that you modify or obtain the modification of the passports used, in order to obtain more accurate and qualitative reports.

	Deposit name	Error explanation
⊗	Topper	Conversion factor of functional unit for carbon footprint is missing
⊗	Topper	Could not determine the Embodied Carbon Footprint (A1-A5 + B + C) of this deposit: No Information
⊗	Cintres	Conversion factor of functional unit for carbon footprint is missing
⊗	Cintres	Could not determine the Embodied Carbon Footprint (A1-A5 + B + C) of this deposit: No Information
⊗	Prise	Conversion factor is missing and is necessary
⊗	Prise	Conversion factor of functional unit for carbon footprint is missing
⊗	Poubelle	Conversion factor of functional unit for carbon footprint is missing
⊗	Poubelle	Could not determine the Embodied Carbon Footprint (A1-A5 + B + C) of this deposit: No Information
⊗	chasse d'eau	Conversion factor of functional unit for carbon footprint is missing
⊗	chasse d'eau	Could not determine the Embodied Carbon Footprint (A1-A5 + B + C) of this deposit: No Information
⊗	Topper	Conversion factor of functional unit for carbon footprint is missing
⊗	Topper	Could not determine the Embodied Carbon Footprint (A1-A5 + B + C) of this deposit: No Information
⊗	Function Line TV	Conversion factor of functional unit for carbon footprint is missing
⊗	Function Line TV	Could not determine the Embodied Carbon Footprint (A1-A5 + B + C) of this deposit: No Information
⊗	Piètement de Table	Conversion factor of functional unit for carbon footprint is missing

CARBON FOOTPRINT

ERROR REPORT (56 errors, 403 warnings)

Here are listed the errors and warnings that were generated during the calculation of the report. They are generally linked to insufficient or imprecise filling of product passports.

⚠ - Warning: a data is missing - the concerned deposit has been taken into account but the result of the indicator for this deposit may be non representative or partial

⊗ - Error: an important data is missing - the concerned deposit could not be taken into account in the calculation of the indicator

In both cases, we recommend that you modify or obtain the modification of the passports used, in order to obtain more accurate and qualitative reports.

	Deposit name	Error explanation
⊗	Piètement de Table	Could not determine the Embodied Carbon Footprint (A1-A5 + B + C) of this deposit: No Information
⊗	Applique mural	Conversion factor of functional unit for carbon footprint is missing
⊗	chasse d'eau	Conversion factor of functional unit for carbon footprint is missing
⊗	chasse d'eau	Could not determine the Embodied Carbon Footprint (A1-A5 + B + C) of this deposit: No Information
⊗	Topper	Conversion factor of functional unit for carbon footprint is missing
⊗	Topper	Could not determine the Embodied Carbon Footprint (A1-A5 + B + C) of this deposit: No Information
⊗	Cintres	Conversion factor of functional unit for carbon footprint is missing
⊗	Cintres	Could not determine the Embodied Carbon Footprint (A1-A5 + B + C) of this deposit: No Information
⊗	Prise	Conversion factor is missing and is necessary
⊗	Prise	Conversion factor of functional unit for carbon footprint is missing
⊗	Topper	Conversion factor of functional unit for carbon footprint is missing
⊗	Topper	Could not determine the Embodied Carbon Footprint (A1-A5 + B + C) of this deposit: No Information
⊗	Function Line TV	Conversion factor of functional unit for carbon footprint is missing
⊗	Function Line TV	Could not determine the Embodied Carbon Footprint (A1-A5 + B + C) of this deposit: No Information
⊗	Piètement de Table	Conversion factor of functional unit for carbon footprint is missing

CARBON FOOTPRINT

ERROR REPORT (56 errors, 403 warnings)

Here are listed the errors and warnings that were generated during the calculation of the report. They are generally linked to insufficient or imprecise filling of product passports.

⚠ - Warning: a data is missing - the concerned deposit has been taken into account but the result of the indicator for this deposit may be non representative or partial

⊗ - Error: an important data is missing - the concerned deposit could not be taken into account in the calculation of the indicator

In both cases, we recommend that you modify or obtain the modification of the passports used, in order to obtain more accurate and qualitative reports.

	Deposit name	Error explanation
⊗	Piètement de Table	Could not determine the Embodied Carbon Footprint (A1-A5 + B + C) of this deposit: No Information
⊗	Applique mural	Conversion factor of functional unit for carbon footprint is missing
⊗	Chevets	Conversion factor of functional unit for carbon footprint is missing
⊗	Chevets	Could not determine the Embodied Carbon Footprint (A1-A5 + B + C) of this deposit: No Information
⊗	Penderie	Could not determine the Embodied Carbon Footprint (A1-A5 + B + C) of this deposit: No Information
⊗	Penderie	Could not determine the IC Component Carbon Footprint of this deposit: No Information
⊗	Meuble TV	Conversion factor of functional unit for carbon footprint is missing
⊗	Meuble TV	Could not determine the Embodied Carbon Footprint (A1-A5 + B + C) of this deposit: No Information
⊗	Cintre standard	Conversion factor of functional unit for carbon footprint is missing
⊗	Cintre standard	Could not determine the Embodied Carbon Footprint (A1-A5 + B + C) of this deposit: No Information
⊗	Porte bagages pliable	Conversion factor of functional unit for carbon footprint is missing
⊗	Porte bagages pliable	Could not determine the Embodied Carbon Footprint (A1-A5 + B + C) of this deposit: No Information
⊗	Chevets	Conversion factor of functional unit for carbon footprint is missing
⊗	Chevets	Could not determine the Embodied Carbon Footprint (A1-A5 + B + C) of this deposit: No Information
⊗	Penderie	Could not determine the Embodied Carbon Footprint (A1-A5 + B + C) of this deposit: No Information

CARBON FOOTPRINT

ERROR REPORT (56 errors, 403 warnings)

Here are listed the errors and warnings that were generated during the calculation of the report. They are generally linked to insufficient or imprecise filling of product passports.

 - Warning: a data is missing - the concerned deposit has been taken into account but the result of the indicator for this deposit may be non representative or partial

 - Error: an important data is missing - the concerned deposit could not be taken into account in the calculation of the indicator

In both cases, we recommend that you modify or obtain the modification of the passports used, in order to obtain more accurate and qualitative reports.

	Deposit name	Error explanation
	Penderie	Could not determine the IC Component Carbon Footprint of this deposit: No Information
	Meuble TV	Conversion factor of functional unit for carbon footprint is missing
	Meuble TV	Could not determine the Embodied Carbon Footprint (A1-A5 + B + C) of this deposit: No Information
	Cintre standard	Conversion factor of functional unit for carbon footprint is missing
	Cintre standard	Could not determine the Embodied Carbon Footprint (A1-A5 + B + C) of this deposit: No Information
	Porte bagages pliable	Conversion factor of functional unit for carbon footprint is missing
	Porte bagages pliable	Could not determine the Embodied Carbon Footprint (A1-A5 + B + C) of this deposit: No Information
	Chevet-Tabouret	Could not determine the Embodied Carbon Footprint (A1-A5 + B + C) of this deposit: No Information
	Chevet-Tabouret	Could not determine the IC Component Carbon Footprint of this deposit: No Information
	Chevet-Tabouret	Could not determine the Embodied Carbon Footprint (A1-A5 + B + C) of this deposit: No Information
	Chevet-Tabouret	Could not determine the IC Component Carbon Footprint of this deposit: No Information
	Peinture Murs et Plafond	The carbon footprint of Resource Recovery Stage (D module) is missing
	Revêtement de sol	The carbon footprint of Resource Recovery Stage (D module) is missing
	Chaise	The carbon footprint of Use Stage (B1-B5) is missing
	Chaise	The carbon footprint of Resource Recovery Stage (D module) is missing

CARBON FOOTPRINT

ERROR REPORT (56 errors, 403 warnings)

Here are listed the errors and warnings that were generated during the calculation of the report. They are generally linked to insufficient or imprecise filling of product passports.

 - Warning: a data is missing - the concerned deposit has been taken into account but the result of the indicator for this deposit may be non representative or partial

 - Error: an important data is missing - the concerned deposit could not be taken into account in the calculation of the indicator

In both cases, we recommend that you modify or obtain the modification of the passports used, in order to obtain more accurate and qualitative reports.

	Deposit name	Error explanation
	Chaise	The period of use was considered to be 50 years because it was not indicated in the circular passport
	Rideaux	The carbon footprint of Resource Recovery Stage (D module) is missing
	Tête de lit	The carbon footprint of construction process stage (A4-A5) is missing
	Tête de lit	The carbon footprint of Use Stage (B1-B5) is missing
	Tête de lit	The carbon footprint of End-of-life stage (C1-C4) is missing
	Tête de lit	The carbon footprint of Resource Recovery Stage (D module) is missing
	Topper	The carbon footprint of raw material and manufacturing (product stage - A1-A3) is missing
	Topper	The carbon footprint of construction process stage (A4-A5) is missing
	Topper	The carbon footprint of Use Stage (B1-B5) is missing
	Topper	The carbon footprint of End-of-life stage (C1-C4) is missing
	Topper	The carbon footprint of Resource Recovery Stage (D module) is missing
	Matelas	The carbon footprint of construction process stage (A4-A5) is missing
	Matelas	The carbon footprint of Use Stage (B1-B5) is missing
	Matelas	The carbon footprint of End-of-life stage (C1-C4) is missing
	Matelas	The carbon footprint of Resource Recovery Stage (D module) is missing

CARBON FOOTPRINT

ERROR REPORT (56 errors, 403 warnings)

Here are listed the errors and warnings that were generated during the calculation of the report. They are generally linked to insufficient or imprecise filling of product passports.

 - Warning: a data is missing - the concerned deposit has been taken into account but the result of the indicator for this deposit may be non representative or partial

 - Error: an important data is missing - the concerned deposit could not be taken into account in the calculation of the indicator

In both cases, we recommend that you modify or obtain the modification of the passports used, in order to obtain more accurate and qualitative reports.

	Deposit name	Error explanation
	Système rail	The carbon footprint of Use Stage (B1-B5) is missing
	Système rail	The carbon footprint of Resource Recovery Stage (D module) is missing
	Plinthe électrique	The carbon footprint of Use Stage (B1-B5) is missing
	Plinthe électrique	The carbon footprint of Resource Recovery Stage (D module) is missing
	Cintres	The carbon footprint of raw material and manufacturing (product stage - A1-A3) is missing
	Cintres	The carbon footprint of construction process stage (A4-A5) is missing
	Cintres	The carbon footprint of Use Stage (B1-B5) is missing
	Cintres	The carbon footprint of End-of-life stage (C1-C4) is missing
	Cintres	The carbon footprint of Resource Recovery Stage (D module) is missing
	Interrupteur	The carbon footprint of Resource Recovery Stage (D module) is missing
	Prise	The carbon footprint of Resource Recovery Stage (D module) is missing
	Applique tête de lit	The carbon footprint of Use Stage (B1-B5) is missing
	Applique tête de lit	The carbon footprint of Resource Recovery Stage (D module) is missing
	Applique tête de lit	The period of use was considered to be 50 years because it was not indicated in the circular passport
	Applique miroir	The carbon footprint of Use Stage (B1-B5) is missing

CARBON FOOTPRINT

ERROR REPORT (56 errors, 403 warnings)

Here are listed the errors and warnings that were generated during the calculation of the report. They are generally linked to insufficient or imprecise filling of product passports.

 - Warning: a data is missing - the concerned deposit has been taken into account but the result of the indicator for this deposit may be non representative or partial

 - Error: an important data is missing - the concerned deposit could not be taken into account in the calculation of the indicator

In both cases, we recommend that you modify or obtain the modification of the passports used, in order to obtain more accurate and qualitative reports.

	Deposit name	Error explanation
	Applique miroir	The carbon footprint of Resource Recovery Stage (D module) is missing
	Applique miroir	The period of use was considered to be 50 years because it was not indicated in the circular passport
	Applique bureau	The carbon footprint of Use Stage (B1-B5) is missing
	Applique bureau	The carbon footprint of Resource Recovery Stage (D module) is missing
	Applique bureau	The period of use was considered to be 50 years because it was not indicated in the circular passport
	Banquette	The carbon footprint of Use Stage (B1-B5) is missing
	Banquette	The carbon footprint of Resource Recovery Stage (D module) is missing
	Banquette	The period of use was considered to be 50 years because it was not indicated in the circular passport
	Chaise pliante	The carbon footprint of Use Stage (B1-B5) is missing
	Chaise pliante	The carbon footprint of Resource Recovery Stage (D module) is missing
	Chaise pliante	The period of use was considered to be 50 years because it was not indicated in the circular passport
	Store d'occultation	The carbon footprint of Use Stage (B1-B5) is missing
	Store d'occultation	The carbon footprint of Resource Recovery Stage (D module) is missing
	Spot bureau	The carbon footprint of Resource Recovery Stage (D module) is missing
	revêtement de sol	The carbon footprint of Use Stage (B1-B5) is missing

CARBON FOOTPRINT

ERROR REPORT (56 errors, 403 warnings)

Here are listed the errors and warnings that were generated during the calculation of the report. They are generally linked to insufficient or imprecise filling of product passports.

 - Warning: a data is missing - the concerned deposit has been taken into account but the result of the indicator for this deposit may be non representative or partial

 - Error: an important data is missing - the concerned deposit could not be taken into account in the calculation of the indicator

In both cases, we recommend that you modify or obtain the modification of the passports used, in order to obtain more accurate and qualitative reports.

	Deposit name	Error explanation
	revêtement de sol	The carbon footprint of Resource Recovery Stage (D module) is missing
	Dalle minérale	The carbon footprint of Resource Recovery Stage (D module) is missing
	MITIGEUR LAVABO	The carbon footprint of Resource Recovery Stage (D module) is missing
	WC suspendu	The carbon footprint of Use Stage (B1-B5) is missing
	WC suspendu	The carbon footprint of Resource Recovery Stage (D module) is missing
	BATI SUPPORT WC	The carbon footprint of Use Stage (B1-B5) is missing
	BATI SUPPORT WC	The carbon footprint of Resource Recovery Stage (D module) is missing
	Vasque	The carbon footprint of construction process stage (A4-A5) is missing
	Vasque	The carbon footprint of Use Stage (B1-B5) is missing
	Vasque	The carbon footprint of Resource Recovery Stage (D module) is missing
	miroir	The carbon footprint of Resource Recovery Stage (D module) is missing
	Poubelle	The carbon footprint of raw material and manufacturing (product stage - A1-A3) is missing
	Poubelle	The carbon footprint of construction process stage (A4-A5) is missing
	Poubelle	The carbon footprint of Use Stage (B1-B5) is missing
	Poubelle	The carbon footprint of End-of-life stage (C1-C4) is missing

CARBON FOOTPRINT

ERROR REPORT (56 errors, 403 warnings)

Here are listed the errors and warnings that were generated during the calculation of the report. They are generally linked to insufficient or imprecise filling of product passports.

 - Warning: a data is missing - the concerned deposit has been taken into account but the result of the indicator for this deposit may be non representative or partial

 - Error: an important data is missing - the concerned deposit could not be taken into account in the calculation of the indicator

In both cases, we recommend that you modify or obtain the modification of the passports used, in order to obtain more accurate and qualitative reports.

	Deposit name	Error explanation
	Poubelle	The carbon footprint of Resource Recovery Stage (D module) is missing
	Poubelle	The period of use was considered to be 50 years because it was not indicated in the circular passport
	Patère simple	The carbon footprint of construction process stage (A4-A5) is missing
	Patère simple	The carbon footprint of Use Stage (B1-B5) is missing
	Patère simple	The carbon footprint of Resource Recovery Stage (D module) is missing
	Porte papier	The carbon footprint of construction process stage (A4-A5) is missing
	Porte papier	The carbon footprint of Use Stage (B1-B5) is missing
	Porte papier	The carbon footprint of Resource Recovery Stage (D module) is missing
	chasse d'eau	The carbon footprint of raw material and manufacturing (product stage - A1-A3) is missing
	chasse d'eau	The carbon footprint of construction process stage (A4-A5) is missing
	chasse d'eau	The carbon footprint of Use Stage (B1-B5) is missing
	chasse d'eau	The carbon footprint of End-of-life stage (C1-C4) is missing
	chasse d'eau	The carbon footprint of Resource Recovery Stage (D module) is missing
	spot	The carbon footprint of Resource Recovery Stage (D module) is missing
	Pot à Balai	The carbon footprint of construction process stage (A4-A5) is missing

CARBON FOOTPRINT

ERROR REPORT (56 errors, 403 warnings)

Here are listed the errors and warnings that were generated during the calculation of the report. They are generally linked to insufficient or imprecise filling of product passports.

 - Warning: a data is missing - the concerned deposit has been taken into account but the result of the indicator for this deposit may be non representative or partial

 - Error: an important data is missing - the concerned deposit could not be taken into account in the calculation of the indicator

In both cases, we recommend that you modify or obtain the modification of the passports used, in order to obtain more accurate and qualitative reports.

	Deposit name	Error explanation
	Pot à Balai	The carbon footprint of Use Stage (B1-B5) is missing
	Pot à Balai	The carbon footprint of Resource Recovery Stage (D module) is missing
	Bac à douche	The carbon footprint of construction process stage (A4-A5) is missing
	Bac à douche	The carbon footprint of Use Stage (B1-B5) is missing
	Bac à douche	The carbon footprint of Resource Recovery Stage (D module) is missing
	Moquette	The carbon footprint of Use Stage (B1-B5) is missing
	Moquette	The carbon footprint of Resource Recovery Stage (D module) is missing
	Penderie	The carbon footprint of Use Stage (B1-B5) is missing
	Penderie	The carbon footprint of End-of-life stage (C1-C4) is missing
	Penderie	The carbon footprint of Resource Recovery Stage (D module) is missing
	Chaise	The carbon footprint of construction process stage (A4-A5) is missing
	Chaise	The carbon footprint of Use Stage (B1-B5) is missing
	Chaise	The carbon footprint of Resource Recovery Stage (D module) is missing
	Rideaux	The carbon footprint of Use Stage (B1-B5) is missing
	Rideaux	The carbon footprint of Resource Recovery Stage (D module) is missing

CARBON FOOTPRINT

ERROR REPORT (56 errors, 403 warnings)

Here are listed the errors and warnings that were generated during the calculation of the report. They are generally linked to insufficient or imprecise filling of product passports.

 - Warning: a data is missing - the concerned deposit has been taken into account but the result of the indicator for this deposit may be non representative or partial

 - Error: an important data is missing - the concerned deposit could not be taken into account in the calculation of the indicator

In both cases, we recommend that you modify or obtain the modification of the passports used, in order to obtain more accurate and qualitative reports.

	Deposit name	Error explanation
	tête de lit	The carbon footprint of construction process stage (A4-A5) is missing
	tête de lit	The carbon footprint of Use Stage (B1-B5) is missing
	tête de lit	The carbon footprint of End-of-life stage (C1-C4) is missing
	tête de lit	The carbon footprint of Resource Recovery Stage (D module) is missing
	tête de lit	Category is not precise, it will affect data visualization
	Topper	The carbon footprint of raw material and manufacturing (product stage - A1-A3) is missing
	Topper	The carbon footprint of construction process stage (A4-A5) is missing
	Topper	The carbon footprint of Use Stage (B1-B5) is missing
	Topper	The carbon footprint of End-of-life stage (C1-C4) is missing
	Topper	The carbon footprint of Resource Recovery Stage (D module) is missing
	Matelas	The carbon footprint of construction process stage (A4-A5) is missing
	Matelas	The carbon footprint of Use Stage (B1-B5) is missing
	Matelas	The carbon footprint of End-of-life stage (C1-C4) is missing
	Matelas	The carbon footprint of Resource Recovery Stage (D module) is missing
	Sommier	The carbon footprint of construction process stage (A4-A5) is missing

CARBON FOOTPRINT

ERROR REPORT (56 errors, 403 warnings)

Here are listed the errors and warnings that were generated during the calculation of the report. They are generally linked to insufficient or imprecise filling of product passports.

 - Warning: a data is missing - the concerned deposit has been taken into account but the result of the indicator for this deposit may be non representative or partial

 - Error: an important data is missing - the concerned deposit could not be taken into account in the calculation of the indicator

In both cases, we recommend that you modify or obtain the modification of the passports used, in order to obtain more accurate and qualitative reports.

	Deposit name	Error explanation
	Sommier	The carbon footprint of Use Stage (B1-B5) is missing
	Sommier	The carbon footprint of End-of-life stage (C1-C4) is missing
	Sommier	The carbon footprint of Resource Recovery Stage (D module) is missing
	Rail pour rideau	The carbon footprint of Use Stage (B1-B5) is missing
	Rail pour rideau	The carbon footprint of Resource Recovery Stage (D module) is missing
	Plinthe électrique	The carbon footprint of Use Stage (B1-B5) is missing
	Plinthe électrique	The carbon footprint of Resource Recovery Stage (D module) is missing
	Radiofrequency switch	The carbon footprint of Resource Recovery Stage (D module) is missing
	PLUG DOCK	The carbon footprint of Use Stage (B1-B5) is missing
	PLUG DOCK	The carbon footprint of Resource Recovery Stage (D module) is missing
	Socket USB	The carbon footprint of Use Stage (B1-B5) is missing
	Socket USB	The carbon footprint of Resource Recovery Stage (D module) is missing
	Function Line TV	The carbon footprint of raw material and manufacturing (product stage - A1-A3) is missing
	Function Line TV	The carbon footprint of construction process stage (A4-A5) is missing
	Function Line TV	The carbon footprint of Use Stage (B1-B5) is missing

CARBON FOOTPRINT

ERROR REPORT (56 errors, 403 warnings)

Here are listed the errors and warnings that were generated during the calculation of the report. They are generally linked to insufficient or imprecise filling of product passports.

 - Warning: a data is missing - the concerned deposit has been taken into account but the result of the indicator for this deposit may be non representative or partial

 - Error: an important data is missing - the concerned deposit could not be taken into account in the calculation of the indicator

In both cases, we recommend that you modify or obtain the modification of the passports used, in order to obtain more accurate and qualitative reports.

	Deposit name	Error explanation
	Function Line TV	The carbon footprint of End-of-life stage (C1-C4) is missing
	Function Line TV	The carbon footprint of Resource Recovery Stage (D module) is missing
	Floor lamp	The carbon footprint of construction process stage (A4-A5) is missing
	Floor lamp	The carbon footprint of Use Stage (B1-B5) is missing
	Floor lamp	The carbon footprint of End-of-life stage (C1-C4) is missing
	Floor lamp	The carbon footprint of Resource Recovery Stage (D module) is missing
	Piètement de Table	The carbon footprint of raw material and manufacturing (product stage - A1-A3) is missing
	Piètement de Table	The carbon footprint of construction process stage (A4-A5) is missing
	Piètement de Table	The carbon footprint of Use Stage (B1-B5) is missing
	Piètement de Table	The carbon footprint of End-of-life stage (C1-C4) is missing
	Piètement de Table	The carbon footprint of Resource Recovery Stage (D module) is missing
	Piètement de Table	Category is not precise, it will affect data visualization
	Spot	The carbon footprint of Resource Recovery Stage (D module) is missing
	Applique mural	The carbon footprint of construction process stage (A4-A5) is missing
	Applique mural	The carbon footprint of Use Stage (B1-B5) is missing

CARBON FOOTPRINT

ERROR REPORT (56 errors, 403 warnings)

Here are listed the errors and warnings that were generated during the calculation of the report. They are generally linked to insufficient or imprecise filling of product passports.

 - Warning: a data is missing - the concerned deposit has been taken into account but the result of the indicator for this deposit may be non representative or partial

 - Error: an important data is missing - the concerned deposit could not be taken into account in the calculation of the indicator

In both cases, we recommend that you modify or obtain the modification of the passports used, in order to obtain more accurate and qualitative reports.

	Deposit name	Error explanation
	Applique mural	The carbon footprint of End-of-life stage (C1-C4) is missing
	Applique mural	The period of use was considered to be 50 years because it was not indicated in the circular passport
	Applique mural	The carbon footprint of Use Stage (B1-B5) is missing
	Applique mural	The carbon footprint of Resource Recovery Stage (D module) is missing
	Applique mural	The period of use was considered to be 50 years because it was not indicated in the circular passport
	WALL MIROIR SUSPENDED ON TV FUNCTION LINE	The carbon footprint of Use Stage (B1-B5) is missing
	WALL MIROIR SUSPENDED ON TV FUNCTION LINE	The carbon footprint of Resource Recovery Stage (D module) is missing
	Latte métal	The carbon footprint of construction process stage (A4-A5) is missing
	Latte métal	The carbon footprint of Use Stage (B1-B5) is missing
	Latte métal	The carbon footprint of Resource Recovery Stage (D module) is missing
	Latte métal	The period of use was considered to be 50 years because it was not indicated in the circular passport
	MITIGEUR LAVABO	The carbon footprint of construction process stage (A4-A5) is missing
	MITIGEUR LAVABO	The carbon footprint of Use Stage (B1-B5) is missing
	MITIGEUR LAVABO	The carbon footprint of End-of-life stage (C1-C4) is missing
	MITIGEUR LAVABO	The carbon footprint of Resource Recovery Stage (D module) is missing

CARBON FOOTPRINT

ERROR REPORT (56 errors, 403 warnings)

Here are listed the errors and warnings that were generated during the calculation of the report. They are generally linked to insufficient or imprecise filling of product passports.

⚠ - Warning: a data is missing - the concerned deposit has been taken into account but the result of the indicator for this deposit may be non representative or partial

⊗ - Error: an important data is missing - the concerned deposit could not be taken into account in the calculation of the indicator

In both cases, we recommend that you modify or obtain the modification of the passports used, in order to obtain more accurate and qualitative reports.

	Deposit name	Error explanation
⚠	mitigeur douche	The carbon footprint of construction process stage (A4-A5) is missing
⚠	mitigeur douche	The carbon footprint of Use Stage (B1-B5) is missing
⚠	mitigeur douche	The carbon footprint of End-of-life stage (C1-C4) is missing
⚠	mitigeur douche	The carbon footprint of Resource Recovery Stage (D module) is missing
⚠	CUVETTE DE TOILETTE	The carbon footprint of Use Stage (B1-B5) is missing
⚠	CUVETTE DE TOILETTE	The carbon footprint of Resource Recovery Stage (D module) is missing
⚠	BATI SUPPORT WC	The carbon footprint of Use Stage (B1-B5) is missing
⚠	BATI SUPPORT WC	The carbon footprint of Resource Recovery Stage (D module) is missing
⚠	Vasque	The carbon footprint of Resource Recovery Stage (D module) is missing
⚠	Miroir lumineux	The carbon footprint of Use Stage (B1-B5) is missing
⚠	Miroir lumineux	The carbon footprint of Resource Recovery Stage (D module) is missing
⚠	Poubelle	The carbon footprint of construction process stage (A4-A5) is missing
⚠	Poubelle	The carbon footprint of Use Stage (B1-B5) is missing
⚠	Poubelle	The carbon footprint of Resource Recovery Stage (D module) is missing
⚠	Patère simple	The carbon footprint of construction process stage (A4-A5) is missing

CARBON FOOTPRINT

ERROR REPORT (56 errors, 403 warnings)

Here are listed the errors and warnings that were generated during the calculation of the report. They are generally linked to insufficient or imprecise filling of product passports.

 - Warning: a data is missing - the concerned deposit has been taken into account but the result of the indicator for this deposit may be non representative or partial

 - Error: an important data is missing - the concerned deposit could not be taken into account in the calculation of the indicator

In both cases, we recommend that you modify or obtain the modification of the passports used, in order to obtain more accurate and qualitative reports.

	Deposit name	Error explanation
	Patère simple	The carbon footprint of Use Stage (B1-B5) is missing
	Patère simple	The carbon footprint of Resource Recovery Stage (D module) is missing
	Porte papier	The carbon footprint of construction process stage (A4-A5) is missing
	Porte papier	The carbon footprint of Use Stage (B1-B5) is missing
	Porte papier	The carbon footprint of Resource Recovery Stage (D module) is missing
	chasse d'eau	The carbon footprint of raw material and manufacturing (product stage - A1-A3) is missing
	chasse d'eau	The carbon footprint of construction process stage (A4-A5) is missing
	chasse d'eau	The carbon footprint of Use Stage (B1-B5) is missing
	chasse d'eau	The carbon footprint of End-of-life stage (C1-C4) is missing
	chasse d'eau	The carbon footprint of Resource Recovery Stage (D module) is missing
	Spot	The carbon footprint of Resource Recovery Stage (D module) is missing
	Pot à Balai	The carbon footprint of construction process stage (A4-A5) is missing
	Pot à Balai	The carbon footprint of Use Stage (B1-B5) is missing
	Pot à Balai	The carbon footprint of Resource Recovery Stage (D module) is missing
	Bac à douche	The carbon footprint of construction process stage (A4-A5) is missing

CARBON FOOTPRINT

ERROR REPORT (56 errors, 403 warnings)

Here are listed the errors and warnings that were generated during the calculation of the report. They are generally linked to insufficient or imprecise filling of product passports.

 - Warning: a data is missing - the concerned deposit has been taken into account but the result of the indicator for this deposit may be non representative or partial

 - Error: an important data is missing - the concerned deposit could not be taken into account in the calculation of the indicator

In both cases, we recommend that you modify or obtain the modification of the passports used, in order to obtain more accurate and qualitative reports.

	Deposit name	Error explanation
	Bac à douche	The carbon footprint of Use Stage (B1-B5) is missing
	Bac à douche	The carbon footprint of Resource Recovery Stage (D module) is missing
	Peinture Murs et Plafond	The carbon footprint of Resource Recovery Stage (D module) is missing
	Revêtement de sol	The carbon footprint of Resource Recovery Stage (D module) is missing
	Chaise	The carbon footprint of Use Stage (B1-B5) is missing
	Chaise	The carbon footprint of Resource Recovery Stage (D module) is missing
	Chaise	The period of use was considered to be 50 years because it was not indicated in the circular passport
	Rideaux	The carbon footprint of Resource Recovery Stage (D module) is missing
	Tête de lit	The carbon footprint of construction process stage (A4-A5) is missing
	Tête de lit	The carbon footprint of Use Stage (B1-B5) is missing
	Tête de lit	The carbon footprint of End-of-life stage (C1-C4) is missing
	Tête de lit	The carbon footprint of Resource Recovery Stage (D module) is missing
	Topper	The carbon footprint of raw material and manufacturing (product stage - A1-A3) is missing
	Topper	The carbon footprint of construction process stage (A4-A5) is missing
	Topper	The carbon footprint of Use Stage (B1-B5) is missing

CARBON FOOTPRINT

ERROR REPORT (56 errors, 403 warnings)

Here are listed the errors and warnings that were generated during the calculation of the report. They are generally linked to insufficient or imprecise filling of product passports.

 - Warning: a data is missing - the concerned deposit has been taken into account but the result of the indicator for this deposit may be non representative or partial

 - Error: an important data is missing - the concerned deposit could not be taken into account in the calculation of the indicator

In both cases, we recommend that you modify or obtain the modification of the passports used, in order to obtain more accurate and qualitative reports.

	Deposit name	Error explanation
	Topper	The carbon footprint of End-of-life stage (C1-C4) is missing
	Topper	The carbon footprint of Resource Recovery Stage (D module) is missing
	Matelas	The carbon footprint of construction process stage (A4-A5) is missing
	Matelas	The carbon footprint of Use Stage (B1-B5) is missing
	Matelas	The carbon footprint of End-of-life stage (C1-C4) is missing
	Matelas	The carbon footprint of Resource Recovery Stage (D module) is missing
	Système rail	The carbon footprint of Use Stage (B1-B5) is missing
	Système rail	The carbon footprint of Resource Recovery Stage (D module) is missing
	Plinthe électrique	The carbon footprint of Use Stage (B1-B5) is missing
	Plinthe électrique	The carbon footprint of Resource Recovery Stage (D module) is missing
	Cintres	The carbon footprint of raw material and manufacturing (product stage - A1-A3) is missing
	Cintres	The carbon footprint of construction process stage (A4-A5) is missing
	Cintres	The carbon footprint of Use Stage (B1-B5) is missing
	Cintres	The carbon footprint of End-of-life stage (C1-C4) is missing
	Cintres	The carbon footprint of Resource Recovery Stage (D module) is missing

CARBON FOOTPRINT

ERROR REPORT (56 errors, 403 warnings)

Here are listed the errors and warnings that were generated during the calculation of the report. They are generally linked to insufficient or imprecise filling of product passports.

 - Warning: a data is missing - the concerned deposit has been taken into account but the result of the indicator for this deposit may be non representative or partial

 - Error: an important data is missing - the concerned deposit could not be taken into account in the calculation of the indicator

In both cases, we recommend that you modify or obtain the modification of the passports used, in order to obtain more accurate and qualitative reports.

	Deposit name	Error explanation
	Interrupteur	The carbon footprint of Resource Recovery Stage (D module) is missing
	Prise	The carbon footprint of Resource Recovery Stage (D module) is missing
	Applique tête de lit	The carbon footprint of Use Stage (B1-B5) is missing
	Applique tête de lit	The carbon footprint of Resource Recovery Stage (D module) is missing
	Applique tête de lit	The period of use was considered to be 50 years because it was not indicated in the circular passport
	Applique miroir	The carbon footprint of Use Stage (B1-B5) is missing
	Applique miroir	The carbon footprint of Resource Recovery Stage (D module) is missing
	Applique miroir	The period of use was considered to be 50 years because it was not indicated in the circular passport
	Applique bureau	The carbon footprint of Use Stage (B1-B5) is missing
	Applique bureau	The carbon footprint of Resource Recovery Stage (D module) is missing
	Applique bureau	The period of use was considered to be 50 years because it was not indicated in the circular passport
	Banquette	The carbon footprint of Use Stage (B1-B5) is missing
	Banquette	The carbon footprint of Resource Recovery Stage (D module) is missing
	Banquette	The period of use was considered to be 50 years because it was not indicated in the circular passport
	Chaise pliante	The carbon footprint of Use Stage (B1-B5) is missing

CARBON FOOTPRINT

ERROR REPORT (56 errors, 403 warnings)

Here are listed the errors and warnings that were generated during the calculation of the report. They are generally linked to insufficient or imprecise filling of product passports.

 - Warning: a data is missing - the concerned deposit has been taken into account but the result of the indicator for this deposit may be non representative or partial

 - Error: an important data is missing - the concerned deposit could not be taken into account in the calculation of the indicator

In both cases, we recommend that you modify or obtain the modification of the passports used, in order to obtain more accurate and qualitative reports.

	Deposit name	Error explanation
	Chaise pliante	The carbon footprint of Resource Recovery Stage (D module) is missing
	Chaise pliante	The period of use was considered to be 50 years because it was not indicated in the circular passport
	Store d'occultation	The carbon footprint of Use Stage (B1-B5) is missing
	Store d'occultation	The carbon footprint of Resource Recovery Stage (D module) is missing
	Spot bureau	The carbon footprint of Resource Recovery Stage (D module) is missing
	Moquette	The carbon footprint of Use Stage (B1-B5) is missing
	Moquette	The carbon footprint of Resource Recovery Stage (D module) is missing
	Penderie	The carbon footprint of Use Stage (B1-B5) is missing
	Penderie	The carbon footprint of End-of-life stage (C1-C4) is missing
	Penderie	The carbon footprint of Resource Recovery Stage (D module) is missing
	Chaise	The carbon footprint of construction process stage (A4-A5) is missing
	Chaise	The carbon footprint of Use Stage (B1-B5) is missing
	Chaise	The carbon footprint of Resource Recovery Stage (D module) is missing
	Rideaux	The carbon footprint of Use Stage (B1-B5) is missing
	Rideaux	The carbon footprint of Resource Recovery Stage (D module) is missing

CARBON FOOTPRINT

ERROR REPORT (56 errors, 403 warnings)

Here are listed the errors and warnings that were generated during the calculation of the report. They are generally linked to insufficient or imprecise filling of product passports.

 - Warning: a data is missing - the concerned deposit has been taken into account but the result of the indicator for this deposit may be non representative or partial

 - Error: an important data is missing - the concerned deposit could not be taken into account in the calculation of the indicator

In both cases, we recommend that you modify or obtain the modification of the passports used, in order to obtain more accurate and qualitative reports.

	Deposit name	Error explanation
	tête de lit	The carbon footprint of construction process stage (A4-A5) is missing
	tête de lit	The carbon footprint of Use Stage (B1-B5) is missing
	tête de lit	The carbon footprint of End-of-life stage (C1-C4) is missing
	tête de lit	The carbon footprint of Resource Recovery Stage (D module) is missing
	tête de lit	Category is not precise, it will affect data visualization
	Topper	The carbon footprint of raw material and manufacturing (product stage - A1-A3) is missing
	Topper	The carbon footprint of construction process stage (A4-A5) is missing
	Topper	The carbon footprint of Use Stage (B1-B5) is missing
	Topper	The carbon footprint of End-of-life stage (C1-C4) is missing
	Topper	The carbon footprint of Resource Recovery Stage (D module) is missing
	Matelas	The carbon footprint of construction process stage (A4-A5) is missing
	Matelas	The carbon footprint of Use Stage (B1-B5) is missing
	Matelas	The carbon footprint of End-of-life stage (C1-C4) is missing
	Matelas	The carbon footprint of Resource Recovery Stage (D module) is missing
	Sommier	The carbon footprint of construction process stage (A4-A5) is missing

CARBON FOOTPRINT

ERROR REPORT (56 errors, 403 warnings)

Here are listed the errors and warnings that were generated during the calculation of the report. They are generally linked to insufficient or imprecise filling of product passports.

 - Warning: a data is missing - the concerned deposit has been taken into account but the result of the indicator for this deposit may be non representative or partial

 - Error: an important data is missing - the concerned deposit could not be taken into account in the calculation of the indicator

In both cases, we recommend that you modify or obtain the modification of the passports used, in order to obtain more accurate and qualitative reports.

	Deposit name	Error explanation
	Sommier	The carbon footprint of Use Stage (B1-B5) is missing
	Sommier	The carbon footprint of End-of-life stage (C1-C4) is missing
	Sommier	The carbon footprint of Resource Recovery Stage (D module) is missing
	Rail pour rideau	The carbon footprint of Use Stage (B1-B5) is missing
	Rail pour rideau	The carbon footprint of Resource Recovery Stage (D module) is missing
	Plinthe électrique	The carbon footprint of Use Stage (B1-B5) is missing
	Plinthe électrique	The carbon footprint of Resource Recovery Stage (D module) is missing
	Radiofrequency switch	The carbon footprint of Resource Recovery Stage (D module) is missing
	PLUG DOCK	The carbon footprint of Use Stage (B1-B5) is missing
	PLUG DOCK	The carbon footprint of Resource Recovery Stage (D module) is missing
	Socket USB	The carbon footprint of Use Stage (B1-B5) is missing
	Socket USB	The carbon footprint of Resource Recovery Stage (D module) is missing
	Function Line TV	The carbon footprint of raw material and manufacturing (product stage - A1-A3) is missing
	Function Line TV	The carbon footprint of construction process stage (A4-A5) is missing
	Function Line TV	The carbon footprint of Use Stage (B1-B5) is missing

CARBON FOOTPRINT

ERROR REPORT (56 errors, 403 warnings)

Here are listed the errors and warnings that were generated during the calculation of the report. They are generally linked to insufficient or imprecise filling of product passports.

 - Warning: a data is missing - the concerned deposit has been taken into account but the result of the indicator for this deposit may be non representative or partial

 - Error: an important data is missing - the concerned deposit could not be taken into account in the calculation of the indicator

In both cases, we recommend that you modify or obtain the modification of the passports used, in order to obtain more accurate and qualitative reports.

	Deposit name	Error explanation
	Function Line TV	The carbon footprint of End-of-life stage (C1-C4) is missing
	Function Line TV	The carbon footprint of Resource Recovery Stage (D module) is missing
	Floor lamp	The carbon footprint of construction process stage (A4-A5) is missing
	Floor lamp	The carbon footprint of Use Stage (B1-B5) is missing
	Floor lamp	The carbon footprint of End-of-life stage (C1-C4) is missing
	Floor lamp	The carbon footprint of Resource Recovery Stage (D module) is missing
	Piètement de Table	The carbon footprint of raw material and manufacturing (product stage - A1-A3) is missing
	Piètement de Table	The carbon footprint of construction process stage (A4-A5) is missing
	Piètement de Table	The carbon footprint of Use Stage (B1-B5) is missing
	Piètement de Table	The carbon footprint of End-of-life stage (C1-C4) is missing
	Piètement de Table	The carbon footprint of Resource Recovery Stage (D module) is missing
	Piètement de Table	Category is not precise, it will affect data visualization
	Spot	The carbon footprint of Resource Recovery Stage (D module) is missing
	Applique mural	The carbon footprint of construction process stage (A4-A5) is missing
	Applique mural	The carbon footprint of Use Stage (B1-B5) is missing

CARBON FOOTPRINT

ERROR REPORT (56 errors, 403 warnings)

Here are listed the errors and warnings that were generated during the calculation of the report. They are generally linked to insufficient or imprecise filling of product passports.

 - Warning: a data is missing - the concerned deposit has been taken into account but the result of the indicator for this deposit may be non representative or partial

 - Error: an important data is missing - the concerned deposit could not be taken into account in the calculation of the indicator

In both cases, we recommend that you modify or obtain the modification of the passports used, in order to obtain more accurate and qualitative reports.

	Deposit name	Error explanation
	Applique mural	The carbon footprint of End-of-life stage (C1-C4) is missing
	Applique mural	The period of use was considered to be 50 years because it was not indicated in the circular passport
	Applique mural	The carbon footprint of Use Stage (B1-B5) is missing
	Applique mural	The carbon footprint of Resource Recovery Stage (D module) is missing
	Applique mural	The period of use was considered to be 50 years because it was not indicated in the circular passport
	WALL MIROIR SUSPENDED ON TV FUNCTION LINE	The carbon footprint of Use Stage (B1-B5) is missing
	WALL MIROIR SUSPENDED ON TV FUNCTION LINE	The carbon footprint of Resource Recovery Stage (D module) is missing
	Chevets	The carbon footprint of raw material and manufacturing (product stage - A1-A3) is missing
	Chevets	The carbon footprint of construction process stage (A4-A5) is missing
	Chevets	The carbon footprint of Use Stage (B1-B5) is missing
	Chevets	The carbon footprint of End-of-life stage (C1-C4) is missing
	Chevets	The carbon footprint of Resource Recovery Stage (D module) is missing
	Penderie	The carbon footprint of raw material and manufacturing (product stage - A1-A3) is missing
	Penderie	The carbon footprint of construction process stage (A4-A5) is missing
	Penderie	The carbon footprint of Use Stage (B1-B5) is missing

CARBON FOOTPRINT

ERROR REPORT (56 errors, 403 warnings)

Here are listed the errors and warnings that were generated during the calculation of the report. They are generally linked to insufficient or imprecise filling of product passports.

 - Warning: a data is missing - the concerned deposit has been taken into account but the result of the indicator for this deposit may be non representative or partial

 - Error: an important data is missing - the concerned deposit could not be taken into account in the calculation of the indicator

In both cases, we recommend that you modify or obtain the modification of the passports used, in order to obtain more accurate and qualitative reports.

	Deposit name	Error explanation
	Penderie	The carbon footprint of End-of-life stage (C1-C4) is missing
	Penderie	The carbon footprint of Resource Recovery Stage (D module) is missing
	Sommier	The carbon footprint of construction process stage (A4-A5) is missing
	Sommier	The carbon footprint of Use Stage (B1-B5) is missing
	Sommier	The carbon footprint of End-of-life stage (C1-C4) is missing
	Sommier	The carbon footprint of Resource Recovery Stage (D module) is missing
	Meuble TV	The carbon footprint of raw material and manufacturing (product stage - A1-A3) is missing
	Meuble TV	The carbon footprint of construction process stage (A4-A5) is missing
	Meuble TV	The carbon footprint of Use Stage (B1-B5) is missing
	Meuble TV	The carbon footprint of End-of-life stage (C1-C4) is missing
	Meuble TV	The carbon footprint of Resource Recovery Stage (D module) is missing
	Mitigeur douche	The carbon footprint of construction process stage (A4-A5) is missing
	Mitigeur douche	The carbon footprint of Use Stage (B1-B5) is missing
	Mitigeur douche	The carbon footprint of End-of-life stage (C1-C4) is missing
	Mitigeur douche	The carbon footprint of Resource Recovery Stage (D module) is missing

CARBON FOOTPRINT

ERROR REPORT (56 errors, 403 warnings)

Here are listed the errors and warnings that were generated during the calculation of the report. They are generally linked to insufficient or imprecise filling of product passports.

 - Warning: a data is missing - the concerned deposit has been taken into account but the result of the indicator for this deposit may be non representative or partial

 - Error: an important data is missing - the concerned deposit could not be taken into account in the calculation of the indicator

In both cases, we recommend that you modify or obtain the modification of the passports used, in order to obtain more accurate and qualitative reports.

	Deposit name	Error explanation
	Pare douche	The carbon footprint of construction process stage (A4-A5) is missing
	Pare douche	The carbon footprint of Use Stage (B1-B5) is missing
	Pare douche	The carbon footprint of Resource Recovery Stage (D module) is missing
	Cintre standard	The carbon footprint of raw material and manufacturing (product stage - A1-A3) is missing
	Cintre standard	The carbon footprint of construction process stage (A4-A5) is missing
	Cintre standard	The carbon footprint of Use Stage (B1-B5) is missing
	Cintre standard	The carbon footprint of End-of-life stage (C1-C4) is missing
	Cintre standard	The carbon footprint of Resource Recovery Stage (D module) is missing
	Porte bagages pliable	The carbon footprint of raw material and manufacturing (product stage - A1-A3) is missing
	Porte bagages pliable	The carbon footprint of construction process stage (A4-A5) is missing
	Porte bagages pliable	The carbon footprint of Use Stage (B1-B5) is missing
	Porte bagages pliable	The carbon footprint of End-of-life stage (C1-C4) is missing
	Porte bagages pliable	The carbon footprint of Resource Recovery Stage (D module) is missing
	Pare douche	The carbon footprint of construction process stage (A4-A5) is missing
	Pare douche	The carbon footprint of Use Stage (B1-B5) is missing

CARBON FOOTPRINT

ERROR REPORT (56 errors, 403 warnings)

Here are listed the errors and warnings that were generated during the calculation of the report. They are generally linked to insufficient or imprecise filling of product passports.

 - Warning: a data is missing - the concerned deposit has been taken into account but the result of the indicator for this deposit may be non representative or partial

 - Error: an important data is missing - the concerned deposit could not be taken into account in the calculation of the indicator

In both cases, we recommend that you modify or obtain the modification of the passports used, in order to obtain more accurate and qualitative reports.

	Deposit name	Error explanation
	Pare douche	The carbon footprint of Resource Recovery Stage (D module) is missing
	Chevets	The carbon footprint of raw material and manufacturing (product stage - A1-A3) is missing
	Chevets	The carbon footprint of construction process stage (A4-A5) is missing
	Chevets	The carbon footprint of Use Stage (B1-B5) is missing
	Chevets	The carbon footprint of End-of-life stage (C1-C4) is missing
	Chevets	The carbon footprint of Resource Recovery Stage (D module) is missing
	Penderie	The carbon footprint of raw material and manufacturing (product stage - A1-A3) is missing
	Penderie	The carbon footprint of construction process stage (A4-A5) is missing
	Penderie	The carbon footprint of Use Stage (B1-B5) is missing
	Penderie	The carbon footprint of End-of-life stage (C1-C4) is missing
	Penderie	The carbon footprint of Resource Recovery Stage (D module) is missing
	Sommier	The carbon footprint of construction process stage (A4-A5) is missing
	Sommier	The carbon footprint of Use Stage (B1-B5) is missing
	Sommier	The carbon footprint of End-of-life stage (C1-C4) is missing
	Sommier	The carbon footprint of Resource Recovery Stage (D module) is missing

CARBON FOOTPRINT

ERROR REPORT (56 errors, 403 warnings)

Here are listed the errors and warnings that were generated during the calculation of the report. They are generally linked to insufficient or imprecise filling of product passports.

 - Warning: a data is missing - the concerned deposit has been taken into account but the result of the indicator for this deposit may be non representative or partial

 - Error: an important data is missing - the concerned deposit could not be taken into account in the calculation of the indicator

In both cases, we recommend that you modify or obtain the modification of the passports used, in order to obtain more accurate and qualitative reports.

	Deposit name	Error explanation
	Meuble TV	The carbon footprint of raw material and manufacturing (product stage - A1-A3) is missing
	Meuble TV	The carbon footprint of construction process stage (A4-A5) is missing
	Meuble TV	The carbon footprint of Use Stage (B1-B5) is missing
	Meuble TV	The carbon footprint of End-of-life stage (C1-C4) is missing
	Meuble TV	The carbon footprint of Resource Recovery Stage (D module) is missing
	Cintre standard	The carbon footprint of raw material and manufacturing (product stage - A1-A3) is missing
	Cintre standard	The carbon footprint of construction process stage (A4-A5) is missing
	Cintre standard	The carbon footprint of Use Stage (B1-B5) is missing
	Cintre standard	The carbon footprint of End-of-life stage (C1-C4) is missing
	Cintre standard	The carbon footprint of Resource Recovery Stage (D module) is missing
	Porte bagages pliable	The carbon footprint of raw material and manufacturing (product stage - A1-A3) is missing
	Porte bagages pliable	The carbon footprint of construction process stage (A4-A5) is missing
	Porte bagages pliable	The carbon footprint of Use Stage (B1-B5) is missing
	Porte bagages pliable	The carbon footprint of End-of-life stage (C1-C4) is missing
	Porte bagages pliable	The carbon footprint of Resource Recovery Stage (D module) is missing

CARBON FOOTPRINT

ERROR REPORT (56 errors, 403 warnings)

Here are listed the errors and warnings that were generated during the calculation of the report. They are generally linked to insufficient or imprecise filling of product passports.

 - Warning: a data is missing - the concerned deposit has been taken into account but the result of the indicator for this deposit may be non representative or partial

 - Error: an important data is missing - the concerned deposit could not be taken into account in the calculation of the indicator

In both cases, we recommend that you modify or obtain the modification of the passports used, in order to obtain more accurate and qualitative reports.

	Deposit name	Error explanation
	Carrelage sol	The carbon footprint of Use Stage (B1-B5) is missing
	Carrelage sol	The carbon footprint of Resource Recovery Stage (D module) is missing
	Carrelage mural	The carbon footprint of Use Stage (B1-B5) is missing
	Carrelage mural	The carbon footprint of Resource Recovery Stage (D module) is missing
	Bureau	The carbon footprint of Resource Recovery Stage (D module) is missing
	Caisson fenêtre	The carbon footprint of construction process stage (A4-A5) is missing
	Caisson fenêtre	The carbon footprint of Use Stage (B1-B5) is missing
	Caisson fenêtre	The carbon footprint of Resource Recovery Stage (D module) is missing
	Caisson fenêtre	The period of use was considered to be 50 years because it was not indicated in the circular passport
	Bureau	The carbon footprint of Resource Recovery Stage (D module) is missing
	Caisson fenêtre	The carbon footprint of construction process stage (A4-A5) is missing
	Caisson fenêtre	The carbon footprint of Use Stage (B1-B5) is missing
	Caisson fenêtre	The carbon footprint of Resource Recovery Stage (D module) is missing
	Caisson fenêtre	The period of use was considered to be 50 years because it was not indicated in the circular passport
	Panneau miroir	The carbon footprint of Resource Recovery Stage (D module) is missing

CARBON FOOTPRINT

ERROR REPORT (56 errors, 403 warnings)

Here are listed the errors and warnings that were generated during the calculation of the report. They are generally linked to insufficient or imprecise filling of product passports.

 - Warning: a data is missing - the concerned deposit has been taken into account but the result of the indicator for this deposit may be non representative or partial

 - Error: an important data is missing - the concerned deposit could not be taken into account in the calculation of the indicator

In both cases, we recommend that you modify or obtain the modification of the passports used, in order to obtain more accurate and qualitative reports.

	Deposit name	Error explanation
	revêtement de mur (peinture)	The carbon footprint of Resource Recovery Stage (D module) is missing
	Applique mural	The carbon footprint of Use Stage (B1-B5) is missing
	Applique mural	The carbon footprint of Resource Recovery Stage (D module) is missing
	Applique mural	The period of use was considered to be 50 years because it was not indicated in the circular passport
	Chevet-Tabouret	The carbon footprint of raw material and manufacturing (product stage - A1-A3) is missing
	Chevet-Tabouret	The carbon footprint of construction process stage (A4-A5) is missing
	Chevet-Tabouret	The carbon footprint of Use Stage (B1-B5) is missing
	Chevet-Tabouret	The carbon footprint of End-of-life stage (C1-C4) is missing
	Chevet-Tabouret	The carbon footprint of Resource Recovery Stage (D module) is missing
	Panneau miroir	The carbon footprint of Resource Recovery Stage (D module) is missing
	Chevet-Tabouret	The carbon footprint of raw material and manufacturing (product stage - A1-A3) is missing
	Chevet-Tabouret	The carbon footprint of construction process stage (A4-A5) is missing
	Chevet-Tabouret	The carbon footprint of Use Stage (B1-B5) is missing
	Chevet-Tabouret	The carbon footprint of End-of-life stage (C1-C4) is missing
	Chevet-Tabouret	The carbon footprint of Resource Recovery Stage (D module) is missing

CARBON FOOTPRINT

ERROR REPORT (56 errors, 403 warnings)

Here are listed the errors and warnings that were generated during the calculation of the report. They are generally linked to insufficient or imprecise filling of product passports.

 - Warning: a data is missing - the concerned deposit has been taken into account but the result of the indicator for this deposit may be non representative or partial

 - Error: an important data is missing - the concerned deposit could not be taken into account in the calculation of the indicator

In both cases, we recommend that you modify or obtain the modification of the passports used, in order to obtain more accurate and qualitative reports.

	Deposit name	Error explanation
	FAIENCE MURALE	The carbon footprint of Resource Recovery Stage (D module) is missing
	revêtement mural tête de lit	The carbon footprint of Use Stage (B1-B5) is missing
	revêtement mural tête de lit	The carbon footprint of End-of-life stage (C1-C4) is missing
	revêtement mural tête de lit	The carbon footprint of Resource Recovery Stage (D module) is missing
	revêtement mural tête de lit	Category is not precise, it will affect data visualization
	revêtement mural tête de lit	The carbon footprint of Use Stage (B1-B5) is missing
	revêtement mural tête de lit	The carbon footprint of End-of-life stage (C1-C4) is missing
	revêtement mural tête de lit	The carbon footprint of Resource Recovery Stage (D module) is missing
	revêtement mural tête de lit	Category is not precise, it will affect data visualization

