

RESIDUAL VALUE

IN CASE OF REFURBISHMENT

CXC - Métal 57

The financial residual value metric represents what income could potentially be generated by managing your deposits in a circular way. It takes into account the value of the material at the end of the use period, and assumes the additional cost of disposal as well as the savings associated with less waste management (i.e. landfill costs).

The financial residual value in case of refurbishment or retrofit creates an immediate valorisation of all deposits except those related to the structural foundation of the building.

Two scenarios are generated, one prioritizing a maximum uptake of resources (with CO2 and environmental benefits), the other prioritizing economic profitability. Two recovery hypotheses are taken into account: upcycling and reuse. For each deposit, the most profitable hypothesis is chosen.

Please note that the figures given below are based on the information provided in the platform. Incorrect or missing information can lead to unrepresentative results for your deposits.

TWO POSSIBLE SCENARIOS



PROFIT ORIENTED SCENARIO

Residual value obtained by recovering only those materials for which recovery results in an economic benefit compared to conventional waste treatment.



ENVIRONMENT ORIENTED SCENARIO

Residual value in the case where 100% of the materials (including those for which recovery entails an additional cost compared to conventional waste treatment) are recovered.



121 / 155 deposits considered
7,46 tons of deposits in total

RESIDUAL VALUE

IN CASE OF REFURBISHMENT


PROFIT ORIENTED SCENARIO

TOTAL RESIDUAL VALUE



121 / 155 deposits considered
7,46 tons of deposits in total

Percentage of residual value over the initial material cost (%)





RESIDUAL VALUE

IN CASE OF REFURBISHMENT

ALL CATEGORIES (PROFIT ORIENTED SCENARIO)

Percentage of residual value over the initial material cost (%)



RESIDUAL VALUE

IN CASE OF REFURBISHMENT

ALL CATEGORIES (PROFIT ORIENTED SCENARIO)

Category	Number of deposits considered	Weight (Tons)	Percentage of total weight	Residual Value Low hypothesis	Residual Value High hypothesis
Total	121	7,46	100%	7,97	23,1
Furniture and accessories	13	0,292	3,91%	39,0	52,2
Indoor furniture, accessories & décor	15	1,54	20,6%	6,00	21,9
Superstructure	1	0,288	3,86%	0,000	0,000
Partitioning, wall lining & interior insulation	39	1,30	17,4%	1,71	22,9
Floor coverings	2	3,52	47,1%	6,24	23,1
Interior wall coverings	6	0,109	1,46%	0,000	0,000
HVAC & sanitary hot water	9	0,230	3,08%	8,00	8,00
Sanitary equipment	2	0,005	0,064%	2,49	3,18
Electrical installations – CFO/CFA networks	33	0,140	1,88%	4,05	14,3
Technical fabrics	1	0,045	0,606%	0,000	15,5

RESIDUAL VALUE IN CASE OF DECONSTRUCTION

CXC - Métal 57

The financial residual value metric represents what income could potentially be generated by managing your deposits in a circular way. It takes into account the value of the material at the end of the use period, and assumes the additional cost of disposal as well as the savings associated with less waste management (i.e. landfill costs).

The financial residual value in case of deconstruction creates an immediate valorisation of all deposits. Two scenarios are generated, one prioritizing a maximum uptake of resources (with CO2 and environmental benefits), the other prioritizing economic profitability. Two recovery hypotheses are taken into account: upcycling and reuse. For each deposit, the most profitable hypothesis is chosen.

Please note that the figures given below are based on the information provided in the platform. Incorrect or missing information can lead to unrepresentative results for your deposits.

TWO POSSIBLE SCENARIOS




PROFIT ORIENTED SCENARIO

Residual value obtained by recovering only those materials for which recovery results in an economic benefit compared to conventional waste treatment.



ENVIRONMENT ORIENTED SCENARIO

Residual value in the case where 100% of the materials (including those for which recovery entails an additional cost compared to conventional waste treatment) are recovered.



135 / 155 deposits considered
10,5 tons of deposits in total

RESIDUAL VALUE

IN CASE OF DECONSTRUCTION


PROFIT ORIENTED SCENARIO

TOTAL RESIDUAL VALUE



135 / 155 deposits considered
10,5 tons of deposits in total

Percentage of residual value over the initial material cost (%)





RESIDUAL VALUE

IN CASE OF DECONSTRUCTION

ALL CATEGORIES (PROFIT ORIENTED SCENARIO)

Percentage of residual value over the initial material cost (%)



RESIDUAL VALUE

IN CASE OF DECONSTRUCTION

ALL CATEGORIES (PROFIT ORIENTED SCENARIO)

Category	Number of deposits considered	Weight (Tons)	Percentage of total weight	Residual Value Low hypothesis	Residual Value High hypothesis
Total	135	10,5	100%	8,33	23,5
Furniture and accessories	23	1,51	14,4%	40,6	54,0
Indoor furniture, accessories & décor	15	1,54	14,6%	6,00	21,9
Superstructure	1	0,288	2,74%	0,000	0,000
Partitioning, wall lining & interior insulation	39	1,30	12,4%	1,71	22,9
Floor coverings	2	3,52	33,5%	6,24	23,1
Interior wall coverings	8	1,49	14,2%	3,56	4,12
HVAC & sanitary hot water	9	0,230	2,19%	8,00	8,00
Sanitary equipment	2	0,005	0,046%	2,49	3,18
Sanitary systems / networks	1	0,003	0,032%	29,1	37,6
Electrical installations – CFO/CFA networks	34	0,572	5,45%	3,85	16,0
Technical fabrics	1	0,045	0,431%	0,000	15,5

ERROR REPORT (20 errors, 202 warnings)

Here are listed the errors and warnings that were generated during the calculation of the report. They are generally linked to insufficient or imprecise filling of product passports.

⚠ - Warning: a data is missing - the concerned deposit has been taken into account but the result of the indicator for this deposit may be non representative or partial

⊗ - Error: an important data is missing - the concerned deposit could not be taken into account in the calculation of the indicator

In both cases, we recommend that you modify or obtain the modification of the passports used, in order to obtain more accurate and qualitative reports.

Deposit name	Error explanation
⊗ Marmoleum	We lack financial data about this kind of products. Our team will improve shortly our database
⊗ MOB_07 Table mobile Plateau en plancher aluminium échafaudage	This product doesn't match one of our references. Our team will improve shortly our database. Please make sure that your data are representative.
⊗ MOB_19 Gradin Tole aluminium anodisé pliée ep. 2mm rivetée aux gaines	This product doesn't match one of our references. Our team will improve shortly our database. Please make sure that your data are representative.
⊗ FAUTEUIL	This product doesn't match one of our references. Our team will improve shortly our database. Please make sure that your data are representative.
⊗ Rideau salle data - 6 ml à occulter	This product doesn't match one of our references. Our team will improve shortly our database. Please make sure that your data are representative.
⊗ Rideau salle économie circulaire - 4,4 ml à occulter	This product doesn't match one of our references. Our team will improve shortly our database. Please make sure that your data are representative.
⊗ Rideau salle nouveaux matériaux - 4,3 ml à occulter	This product doesn't match one of our references. Our team will improve shortly our database. Please make sure that your data are representative.
⊗ Rideau salle nouveaux matériaux - 5,2 ml à occulter	This product doesn't match one of our references. Our team will improve shortly our database. Please make sure that your data are representative.
⊗ MOB_04 Meuble à tiroirs Tiroirs en plexiglas sur glissières	This product doesn't match one of our references. Our team will improve shortly our database. Please make sure that your data are representative.
⊗ MOB_09 Meuble écran et Pegboard : Panneau Pinboard	This product doesn't match one of our references. Our team will improve shortly our database. Please make sure that your data are representative.
⊗ MOB_18 Compactus mobile config 01 Porte plaqué liège	This product doesn't match one of our references. Our team will improve shortly our database. Please make sure that your data are representative.
⊗ MOB_17 Compactus mobile config 01 Armoire compactable à volant hors étagère et séparateurs verticaux	This product doesn't match one of our references. Our team will improve shortly our database. Please make sure that your data are representative.
⊗ MOB_18 Compactus mobile config 01 Armoire compactable à volant hors étagère et séparateurs verticaux	This product doesn't match one of our references. Our team will improve shortly our database. Please make sure that your data are representative.
⊗ Panneau végétal - Cornière aluminium thermolaqué noir en tête de contre-cloison	This product doesn't match one of our references. Our team will improve shortly our database. Please make sure that your data are representative.
⊗ CLOISONS BA13	This product doesn't match one of our references. Our team will improve shortly our database. Please make sure that your data are representative.

ERROR REPORT (20 errors, 202 warnings)

Here are listed the errors and warnings that were generated during the calculation of the report. They are generally linked to insufficient or imprecise filling of product passports.

⚠ - Warning: a data is missing - the concerned deposit has been taken into account but the result of the indicator for this deposit may be non representative or partial

⊗ - Error: an important data is missing - the concerned deposit could not be taken into account in the calculation of the indicator

In both cases, we recommend that you modify or obtain the modification of the passports used, in order to obtain more accurate and qualitative reports.

	Deposit name	Error explanation
⊗	CONTRE CLOISON PLACO autostable, renforts à prévoir pour la pose des meubles	This product doesn't match one of our references. Our team will improve shortly our database. Please make sure that your data are representative.
⊗	MOB_01 Meuble Coussin d'assise en cuir végétal	This product doesn't match one of our references. Our team will improve shortly our database. Please make sure that your data are representative.
⊗	MOB_02 Assise Coussin d'assise en cuir végétal	This product doesn't match one of our references. Our team will improve shortly our database. Please make sure that your data are representative.
⊗	MOB_03 Assise & Meuble expérience client Coussin d'assise en cuir végétal	This product doesn't match one of our references. Our team will improve shortly our database. Please make sure that your data are representative.
⊗	MOB_19 Gradin Coussins cuir végétal fixation par scratch	This product doesn't match one of our references. Our team will improve shortly our database. Please make sure that your data are representative.
⚠	Moquette de réemploi sur l'ensemble des espaces hormis zone Salon et cuisine Echanger	Purchase price is missing :it may affect the relevance of the financial data
⚠	MOB_20bis Etagère salle nouveaux matériaux L188 x P25cm Kvadrat REALLY cotton blue fixé sur équerre aluminium anodisé	Purchase price is missing :it may affect the relevance of the financial data
⚠	MOB_20bis Etagère salle nouveaux matériaux L188 x P25cm Panneau MDF recouvert de Kvadrat REALLY cotton blue fixé sur équerre aluminium anodisé	Purchase price is missing :it may affect the relevance of the financial data
⚠	Marmoleum	Product was considered as concrete paver financial data might not be relevant
⚠	Marmoleum	Purchase price is missing :it may affect the relevance of the financial data
⚠	Kit Prise double avec plaque carrée intégré au mobilier	Purchase price is missing :it may affect the relevance of the financial data
⚠	Kit Prise triple avec plaque carrée intégré au mobilier	Purchase price is missing :it may affect the relevance of the financial data
⚠	MOB_09 Meuble écran et Pegboard : Bloc prise double	Purchase price is missing :it may affect the relevance of the financial data
⚠	MOB_09 Meuble écran et Pegboard : Bloc prise simple	Purchase price is missing :it may affect the relevance of the financial data
⚠	MOB_10 Meuble écran Bloc prise double	Purchase price is missing :it may affect the relevance of the financial data

ERROR REPORT (20 errors, 202 warnings)

Here are listed the errors and warnings that were generated during the calculation of the report. They are generally linked to insufficient or imprecise filling of product passports.

 - Warning: a data is missing - the concerned deposit has been taken into account but the result of the indicator for this deposit may be non representative or partial

 - Error: an important data is missing - the concerned deposit could not be taken into account in the calculation of the indicator

In both cases, we recommend that you modify or obtain the modification of the passports used, in order to obtain more accurate and qualitative reports.

Deposit name	Error explanation
 MOB_10 Meuble écran Bloc prise simple	Purchase price is missing :it may affect the relevance of the financial data
 Evier en acier inox avec bonde et système complet de commande de bonde	Purchase price is missing :it may affect the relevance of the financial data
 Spots sur rails	Purchase price is missing :it may affect the relevance of the financial data
 Chaîne porte-câble pour alimentation du compactus mobile	Purchase price is missing :it may affect the relevance of the financial data
 Chemin de câble bruts et isolant - voir détails Cornière aluminium thermolaqué noir en tête de contre-cloison	Purchase price is missing :it may affect the relevance of the financial data
 MOB_03 Assise & Meuble expérience client Boitier prise triple - Confidence chrome miroir - 145 en applique - passage de câble par l'intérieur des gaines depuis arrivée au sol dans le plancher	Purchase price is missing :it may affect the relevance of the financial data
 MOB_06 Table mobile LED Bloc prise triple - Confidence chrome miroir - 145 en applique sur le côté	Purchase price is missing :it may affect the relevance of the financial data
 MOB_07 Table mobile Bloc prise triple - Confidence chrome miroir - 145 en applique sur le côté	Purchase price is missing :it may affect the relevance of the financial data
 MOB_16 Table îlot cuisine Prises inox intégrées au plan à clapet étanche	Purchase price is missing :it may affect the relevance of the financial data
 MOB_17 Compactus mobile config 01 Bloc prise	Purchase price is missing :it may affect the relevance of the financial data
 MOB_18 Compactus mobile config 01 Bloc prise	Purchase price is missing :it may affect the relevance of the financial data
 Plateaux de tables rectangulaire L210 x P 140cm Bloc prise triple	Purchase price is missing :it may affect the relevance of the financial data
 Plateaux de tables rectangulaire L360 x P 120cm Bloc prise triple	Purchase price is missing :it may affect the relevance of the financial data
 Prise de sol double avec platine rectangulaire	Purchase price is missing :it may affect the relevance of the financial data
 Prise de sol simple avec platine rectangulaire	Purchase price is missing :it may affect the relevance of the financial data

ERROR REPORT (20 errors, 202 warnings)

Here are listed the errors and warnings that were generated during the calculation of the report. They are generally linked to insufficient or imprecise filling of product passports.

⚠ - Warning: a data is missing - the concerned deposit has been taken into account but the result of the indicator for this deposit may be non representative or partial

⊗ - Error: an important data is missing - the concerned deposit could not be taken into account in the calculation of the indicator

In both cases, we recommend that you modify or obtain the modification of the passports used, in order to obtain more accurate and qualitative reports.

	Deposit name	Error explanation
⚠	Prise double avec platine rectangulaire - intégré à la table cuisine Voir plans électriques	Purchase price is missing :it may affect the relevance of the financial data
⚠	Prise triple crédence avec platine carrée Voir plans électriques	Purchase price is missing :it may affect the relevance of the financial data
⚠	Chaise Noire	Product was considered as concrete paver financial data might not be relevant
⚠	Chaise Noire	Purchase price is missing :it may affect the relevance of the financial data
⚠	TABOURET HAUT	Product was considered as concrete paver financial data might not be relevant
⚠	TABOURET HAUT	Purchase price is missing :it may affect the relevance of the financial data
⚠	CHAISES EMPILABLES RECYCLEES	Product was considered as concrete paver financial data might not be relevant
⚠	CHAISES EMPILABLES RECYCLEES	Purchase price is missing :it may affect the relevance of the financial data
⚠	069 - Table basse	Product was considered as concrete paver financial data might not be relevant
⚠	069 - Table basse	Purchase price is missing :it may affect the relevance of the financial data
⚠	TABLE BASSE	Product was considered as concrete paver financial data might not be relevant
⚠	TABLE BASSE	Purchase price is missing :it may affect the relevance of the financial data
⚠	TABLE SEMI HEXAGONALE	Product was considered as concrete paver financial data might not be relevant
⚠	TABLE SEMI HEXAGONALE	Purchase price is missing :it may affect the relevance of the financial data
⚠	CANAPE	Product was considered as concrete paver financial data might not be relevant

ERROR REPORT (20 errors, 202 warnings)

Here are listed the errors and warnings that were generated during the calculation of the report. They are generally linked to insufficient or imprecise filling of product passports.

 - Warning: a data is missing - the concerned deposit has been taken into account but the result of the indicator for this deposit may be non representative or partial

 - Error: an important data is missing - the concerned deposit could not be taken into account in the calculation of the indicator

In both cases, we recommend that you modify or obtain the modification of the passports used, in order to obtain more accurate and qualitative reports.

Deposit name	Error explanation
 CANAPE	Purchase price is missing :it may affect the relevance of the financial data
 BUREAU REGLABLE	Product was considered as concrete paver financial data might not be relevant
 BUREAU REGLABLE	Purchase price is missing :it may affect the relevance of the financial data
 Habillage miroir	Product was considered as concrete paver financial data might not be relevant
 Habillage miroir	Purchase price is missing :it may affect the relevance of the financial data
 250 - Fauteuils pivotant	Product was considered as concrete paver financial data might not be relevant
 250 - Fauteuils pivotant	Purchase price is missing :it may affect the relevance of the financial data
 250 - Fauteuils pivotant	Product was considered as concrete paver financial data might not be relevant
 250 - Fauteuils pivotant	Purchase price is missing :it may affect the relevance of the financial data
 FAUTEUIL DE BUREAU	Product was considered as concrete paver financial data might not be relevant
 FAUTEUIL DE BUREAU	Purchase price is missing :it may affect the relevance of the financial data
 FAUTEUIL DE BUREAU PIVOTANT	Product was considered as concrete paver financial data might not be relevant
 FAUTEUIL DE BUREAU PIVOTANT	Purchase price is missing :it may affect the relevance of the financial data
 FAUTEUIL DE BUREAU PIVOTANT - 106	Product was considered as concrete paver financial data might not be relevant
 FAUTEUIL DE BUREAU PIVOTANT - 106	Purchase price is missing :it may affect the relevance of the financial data

ERROR REPORT (20 errors, 202 warnings)

Here are listed the errors and warnings that were generated during the calculation of the report. They are generally linked to insufficient or imprecise filling of product passports.

⚠ - Warning: a data is missing - the concerned deposit has been taken into account but the result of the indicator for this deposit may be non representative or partial

⊗ - Error: an important data is missing - the concerned deposit could not be taken into account in the calculation of the indicator

In both cases, we recommend that you modify or obtain the modification of the passports used, in order to obtain more accurate and qualitative reports.

Deposit name	Error explanation
⚠ MOB_01 Meuble Contreplaqué chêne huilé	Purchase price is missing :it may affect the relevance of the financial data
⚠ MOB_04 Meuble à tiroirs Contreplaqué chêne huilé	Purchase price is missing :it may affect the relevance of the financial data
⚠ MOB_04 Meuble à tiroirs Contrplaqué chêne huilé	Purchase price is missing :it may affect the relevance of the financial data
⚠ MOB_05 Divider Panneau contreplaqué chêne huilé pour Bac	Purchase price is missing :it may affect the relevance of the financial data
⚠ MOB_05 Divider Zone centrale menuisée pour support écran et moniteur 65"	Purchase price is missing :it may affect the relevance of the financial data
⚠ MOB_06 Table mobile LED Panneau contreplaqué chêne huilé pour Bac	Purchase price is missing :it may affect the relevance of the financial data
⚠ MOB_07 Table mobile Panneau contreplaqué chêne huilé pour Bac	Purchase price is missing :it may affect the relevance of the financial data
⚠ MOB_08 Bac mobile Panneau contreplaqué chêne huilé sur cornière métallique	Purchase price is missing :it may affect the relevance of the financial data
⚠ MOB_09 Meuble écran et Pegboard Etagères grand et petit modèles CP	Purchase price is missing :it may affect the relevance of the financial data
⚠ MOB_09 Meuble écran et Pegboard : Contreplaqué chêne ép.18mm avec Perforations Ø8mm 30x30mm pour pegboard	Purchase price is missing :it may affect the relevance of the financial data
⚠ MOB_09 Meuble écran et Pegboard : Meuble bas en CP et Porte sur charnières	Purchase price is missing :it may affect the relevance of the financial data
⚠ MOB_09 Meuble écran et Pegboard : Panneau contreplaqué chêne huilé sur cornière métallique et CP pour fixation écran	Purchase price is missing :it may affect the relevance of the financial data
⚠ MOB_10 Meuble écran Meuble bas en CP chêne huilé et Portes sur charnières	Purchase price is missing :it may affect the relevance of the financial data
⚠ MOB_10 Meuble écran Panneau contreplaqué chêne huilé sur cornière métallique et Panneau CP chêne pour fixation écran	Purchase price is missing :it may affect the relevance of the financial data
⚠ MOB_13 Meuble double écran Meuble bas en CP chêne huilé et portes sur charnières	Purchase price is missing :it may affect the relevance of the financial data

ERROR REPORT (20 errors, 202 warnings)

Here are listed the errors and warnings that were generated during the calculation of the report. They are generally linked to insufficient or imprecise filling of product passports.

 - Warning: a data is missing - the concerned deposit has been taken into account but the result of the indicator for this deposit may be non representative or partial

 - Error: an important data is missing - the concerned deposit could not be taken into account in the calculation of the indicator

In both cases, we recommend that you modify or obtain the modification of the passports used, in order to obtain more accurate and qualitative reports.

Deposit name	Error explanation
 MOB_13 Meuble double écran Panneau CP ep.22mm plaqué chêne	Purchase price is missing :it may affect the relevance of the financial data
 MOB_15 Pupitre sur roulettes CP plaqué chêne	Purchase price is missing :it may affect the relevance of the financial data
 MOB_16 Table îlot cuisine CP plaqué chêne	Purchase price is missing :it may affect the relevance of the financial data
 MOB_17 Compactus mobile config 01 Adhésif tableau blanc partie haute, plaqué chêne partie basse	Purchase price is missing :it may affect the relevance of the financial data
 MOB_17 Compactus mobile config 01 Séparateurs verticaux en CP	Purchase price is missing :it may affect the relevance of the financial data
 MOB_17 Compactus mobile config 01 Etagères fixes plaqué chêne	Purchase price is missing :it may affect the relevance of the financial data
 MOB_17 Compactus mobile config 01 Panneau de fond plaqué chêne	Purchase price is missing :it may affect the relevance of the financial data
 MOB_18 Compactus mobile config 01 Séparateur verticaux	Purchase price is missing :it may affect the relevance of the financial data
 MOB_18 Compactus mobile config 01 Etagères plaqué chêne	Purchase price is missing :it may affect the relevance of the financial data
 MOB_20 Barre de penderie salle "nouveaux matériaux" Tube carré 5cm chêne huilé	Purchase price is missing :it may affect the relevance of the financial data
 MOB_20 Barre de penderie salle "végétale" Tube carré 5cm chêne huilé	Purchase price is missing :it may affect the relevance of the financial data
 MOB_20bis L188 x P25cm Etagère panneau de CP plaqué chêne fixée sur équerre aluminium anodisé	Purchase price is missing :it may affect the relevance of the financial data
 MOB_20bis L188 x P25cm Étagère panneau de CP plaqué chêne fixée sur équerre aluminium anodisé	Purchase price is missing :it may affect the relevance of the financial data
 Mitigeur	Purchase price is missing :it may affect the relevance of the financial data
 Mise en peinture blanc côté réserve	Purchase price is missing :it may affect the relevance of the financial data

ERROR REPORT (20 errors, 202 warnings)

Here are listed the errors and warnings that were generated during the calculation of the report. They are generally linked to insufficient or imprecise filling of product passports.

⚠ - Warning: a data is missing - the concerned deposit has been taken into account but the result of the indicator for this deposit may be non representative or partial

⊗ - Error: an important data is missing - the concerned deposit could not be taken into account in the calculation of the indicator

In both cases, we recommend that you modify or obtain the modification of the passports used, in order to obtain more accurate and qualitative reports.

Deposit name	Error explanation
⚠ Mise en peinture blanche porte (entrée) - 2 faces	Purchase price is missing :it may affect the relevance of the financial data
⚠ Mise en peinture Marron dito salle cocréation	Purchase price is missing :it may affect the relevance of the financial data
⚠ PEINTURE Blanc	Purchase price is missing :it may affect the relevance of the financial data
⚠ PEINTURE Marron	Purchase price is missing :it may affect the relevance of the financial data
⚠ PEINTURE Noir en partie haute des cloisons Vulcain	Purchase price is missing :it may affect the relevance of the financial data
⚠ "Plateaux de tables rectangulaire L210 x P 140cm Bloc RJ45	Purchase price is missing :it may affect the relevance of the financial data
⚠ "Plateaux de tables rectangulaire L360 x P 120cm Bloc RJ45	Purchase price is missing :it may affect the relevance of the financial data
⚠ Kit Prise RJ45 avec plaque carrée double intégré au mobilier	Purchase price is missing :it may affect the relevance of the financial data
⚠ Kit Prise RJ45 avec plaque carrée triple intégré au mobilier	Purchase price is missing :it may affect the relevance of the financial data
⚠ MOB_09 Meuble écran et Pegboard : Bloc RJ45 double	Purchase price is missing :it may affect the relevance of the financial data
⚠ MOB_10 Meuble écran Bloc RJ45 double	Purchase price is missing :it may affect the relevance of the financial data
⚠ Prise de sol RJ45 catégorie 6 avec platine rectangulaire	Purchase price is missing :it may affect the relevance of the financial data
⚠ Prise RJ45 double crédence avec platine carrée	Purchase price is missing :it may affect the relevance of the financial data
⚠ MOB_05 Divider Divider vertical en dalles LED 60x60cm - Drivers déportés dans le bac - Film Autocollant Tableau Blanc Smart – Transparent apposé sur les dalles LED	Purchase price is missing :it may affect the relevance of the financial data
⚠ MOB_06 Table mobile LED Plateau en dalles LED 60x60cm et 120x60cm Drivers déportés dans le bac	Purchase price is missing :it may affect the relevance of the financial data

ERROR REPORT (20 errors, 202 warnings)

Here are listed the errors and warnings that were generated during the calculation of the report. They are generally linked to insufficient or imprecise filling of product passports.

 - Warning: a data is missing - the concerned deposit has been taken into account but the result of the indicator for this deposit may be non representative or partial

 - Error: an important data is missing - the concerned deposit could not be taken into account in the calculation of the indicator

In both cases, we recommend that you modify or obtain the modification of the passports used, in order to obtain more accurate and qualitative reports.

Deposit name	Error explanation
 Parquet chêne contrecollé ou massif pose à coupe perdue y compris plinthe	Product was considered as concrete paver financial data might not be relevant
 Parquet chêne contrecollé ou massif pose à coupe perdue y compris plinthe	Purchase price is missing :it may affect the relevance of the financial data
 008 - Pied de table acier chromé (plateau à démonter)	Category is not precise, it will affect data visualization
 008 - Pied de table acier chromé (plateau à démonter)	Purchase price is missing :it may affect the relevance of the financial data
 051 - Pied de table (plateau à démonter)	Category is not precise, it will affect data visualization
 051 - Pied de table (plateau à démonter)	Purchase price is missing :it may affect the relevance of the financial data
 22 - Bureau Bench 6 - 2 Pied métal noir	Category is not precise, it will affect data visualization
 22 - Bureau Bench 6 - 2 Pied métal noir	Purchase price is missing :it may affect the relevance of the financial data
 Piétement bois R+5A	Category is not precise, it will affect data visualization
 Piétement bois R+5A	Purchase price is missing :it may affect the relevance of the financial data
 Plateaux de tables rectangulaire L210 x P 140cm Pieds	Category is not precise, it will affect data visualization
 Plateaux de tables rectangulaire L210 x P 140cm Pieds	Purchase price is missing :it may affect the relevance of the financial data
 Plateaux de tables rectangulaire L360 x P 120cm Pieds	Category is not precise, it will affect data visualization
 Plateaux de tables rectangulaire L360 x P 120cm Pieds	Purchase price is missing :it may affect the relevance of the financial data
 MOB_07 Table mobile Plateau en plancher aluminium échafaudage	Purchase price is missing :it may affect the relevance of the financial data

ERROR REPORT (20 errors, 202 warnings)

Here are listed the errors and warnings that were generated during the calculation of the report. They are generally linked to insufficient or imprecise filling of product passports.

 - Warning: a data is missing - the concerned deposit has been taken into account but the result of the indicator for this deposit may be non representative or partial

 - Error: an important data is missing - the concerned deposit could not be taken into account in the calculation of the indicator

In both cases, we recommend that you modify or obtain the modification of the passports used, in order to obtain more accurate and qualitative reports.

	Deposit name	Error explanation
	MOB_19 Gradin Tole aluminium anodisé pliée ep. 2mm rivetée aux gaines	Purchase price is missing :it may affect the relevance of the financial data
	MOB_15 Pupitre sur roulettes Coulisses pour tablette en inox avec amortisseur	Category is not precise, it will affect data visualization
	MOB_15 Pupitre sur roulettes Coulisses pour tablette en inox avec amortisseur	Product was considered as concrete paver financial data might not be relevant
	MOB_15 Pupitre sur roulettes Coulisses pour tablette en inox avec amortisseur	Purchase price is missing :it may affect the relevance of the financial data
	MOB_04 Meuble à tiroirs Structure tubulaire galvanisé échafaudage composé de : Socle à vis - Montant - Longeron	Category is not precise, it will affect data visualization
	MOB_04 Meuble à tiroirs Structure tubulaire galvanisé échafaudage composé de : Socle à vis - Montant - Longeron	Purchase price is missing :it may affect the relevance of the financial data
	MOB_05 Divider Structure tubulaire galvanisé échafaudage composé de : Socle à vis - Montant - Longeron	Category is not precise, it will affect data visualization
	MOB_05 Divider Structure tubulaire galvanisé échafaudage composé de : Socle à vis - Montant - Longeron	Purchase price is missing :it may affect the relevance of the financial data
	MOB_17 Compactus mobile config 01 Tringle : tube aluminium diam.30mm microbillé	Category is not precise, it will affect data visualization
	MOB_17 Compactus mobile config 01 Tringle : tube aluminium diam.30mm microbillé	Purchase price is missing :it may affect the relevance of the financial data
	MOB_19 Gradin accoudoirs ep. 1mm soudés à la tole alu	Category is not precise, it will affect data visualization
	MOB_19 Gradin accoudoirs ep. 1mm soudés à la tole alu	Purchase price is missing :it may affect the relevance of the financial data
	MOB_03 Assise & Meuble expérience client Gaines galvanisées gaines coudes à section multiple dont une ouverte sur le dessus pour intégrations de plantes en pot	Purchase price is missing :it may affect the relevance of the financial data
	MOB_19 Gradin Gaine Coude 90° découpe circulaire diam. Alu	Purchase price is missing :it may affect the relevance of the financial data
	MOB_19 Gradin Gaines aluminium rivetées section 50x40, long 80	Purchase price is missing :it may affect the relevance of the financial data

ERROR REPORT (20 errors, 202 warnings)

Here are listed the errors and warnings that were generated during the calculation of the report. They are generally linked to insufficient or imprecise filling of product passports.

 - Warning: a data is missing - the concerned deposit has been taken into account but the result of the indicator for this deposit may be non representative or partial

 - Error: an important data is missing - the concerned deposit could not be taken into account in the calculation of the indicator

In both cases, we recommend that you modify or obtain the modification of the passports used, in order to obtain more accurate and qualitative reports.

Deposit name	Error explanation
 MOB_19 Gradin Gaines aluminium rivetées section 50x50, long 80	Purchase price is missing :it may affect the relevance of the financial data
 MOB_19 Gradin Gaines aluminium rivetées section 50x80, long 80	Purchase price is missing :it may affect the relevance of the financial data
 MOB_01 Meuble Structure tubulaire galvanisé échafaudage composé de : Socle à vis - Montant - Longeron	Category is not precise, it will affect data visualization
 MOB_01 Meuble Structure tubulaire galvanisé échafaudage composé de : Socle à vis - Montant - Longeron	Product was considered as concrete paver financial data might not be relevant
 MOB_01 Meuble Structure tubulaire galvanisé échafaudage composé de : Socle à vis - Montant - Longeron	Purchase price is missing :it may affect the relevance of the financial data
 MOB_06 Table mobile LED Structure tubulaire galvanisé échafaudage composé de : Socle à vis - Montant - Longeron	Category is not precise, it will affect data visualization
 MOB_06 Table mobile LED Structure tubulaire galvanisé échafaudage composé de : Socle à vis - Montant - Longeron	Product was considered as concrete paver financial data might not be relevant
 MOB_06 Table mobile LED Structure tubulaire galvanisé échafaudage composé de : Socle à vis - Montant - Longeron	Purchase price is missing :it may affect the relevance of the financial data
 MOB_07 Table mobile Structure tubulaire galvanisé échafaudage composé de : Socle à vis - Montant - Longeron	Category is not precise, it will affect data visualization
 MOB_07 Table mobile Structure tubulaire galvanisé échafaudage composé de : Socle à vis - Montant - Longeron	Product was considered as concrete paver financial data might not be relevant
 MOB_07 Table mobile Structure tubulaire galvanisé échafaudage composé de : Socle à vis - Montant - Longeron	Purchase price is missing :it may affect the relevance of the financial data
 MOB_08 Bac mobile Structure tubulaire galvanisé échafaudage composé de : - Socle à vis avec roue Ø 250mm - Montant - Longeron	Category is not precise, it will affect data visualization
 MOB_08 Bac mobile Structure tubulaire galvanisé échafaudage composé de : - Socle à vis avec roue Ø 250mm - Montant - Longeron	Product was considered as concrete paver financial data might not be relevant
 MOB_08 Bac mobile Structure tubulaire galvanisé échafaudage composé de : - Socle à vis avec roue Ø 250mm - Montant - Longeron	Purchase price is missing :it may affect the relevance of the financial data
 MOB_09 Meuble écran et Pegboard : Structure tubulaire galvanisé échafaudage : - Socle à vis - Montant - Longeron	Category is not precise, it will affect data visualization

ERROR REPORT (20 errors, 202 warnings)

Here are listed the errors and warnings that were generated during the calculation of the report. They are generally linked to insufficient or imprecise filling of product passports.

 - Warning: a data is missing - the concerned deposit has been taken into account but the result of the indicator for this deposit may be non representative or partial

 - Error: an important data is missing - the concerned deposit could not be taken into account in the calculation of the indicator

In both cases, we recommend that you modify or obtain the modification of the passports used, in order to obtain more accurate and qualitative reports.

Deposit name	Error explanation
 MOB_09 Meuble écran et Pegboard : Structure tubulaire galvanisé échafaudage : - Socle à vis - Montant - Longeron	Product was considered as concrete paver financial data might not be relevant
 MOB_09 Meuble écran et Pegboard : Structure tubulaire galvanisé échafaudage : - Socle à vis - Montant - Longeron	Purchase price is missing :it may affect the relevance of the financial data
 MOB_10 Meuble écran Structure tubulaire galvanisé échafaudage : - Socle à vis - Montant - Longeron	Category is not precise, it will affect data visualization
 MOB_10 Meuble écran Structure tubulaire galvanisé échafaudage : - Socle à vis - Montant - Longeron	Product was considered as concrete paver financial data might not be relevant
 MOB_10 Meuble écran Structure tubulaire galvanisé échafaudage : - Socle à vis - Montant - Longeron	Purchase price is missing :it may affect the relevance of the financial data
 MOB_11 Display étagère et cordage V1 Structure tubulaire galvanisé échafaudage : - Socle à vis - Montant - Longeron	Category is not precise, it will affect data visualization
 MOB_11 Display étagère et cordage V1 Structure tubulaire galvanisé échafaudage : - Socle à vis - Montant - Longeron	Product was considered as concrete paver financial data might not be relevant
 MOB_11 Display étagère et cordage V1 Structure tubulaire galvanisé échafaudage : - Socle à vis - Montant - Longeron	Purchase price is missing :it may affect the relevance of the financial data
 MOB_12 Display étagère et cordage V2 Structure tubulaire galvanisé échafaudage : - Socle à vis - Montant - Longeron	Category is not precise, it will affect data visualization
 MOB_12 Display étagère et cordage V2 Structure tubulaire galvanisé échafaudage : - Socle à vis - Montant - Longeron	Product was considered as concrete paver financial data might not be relevant
 MOB_12 Display étagère et cordage V2 Structure tubulaire galvanisé échafaudage : - Socle à vis - Montant - Longeron	Purchase price is missing :it may affect the relevance of the financial data
 MOB_13 Meuble double écran Structure tubulaire galvanisé échafaudage : - Socle à vis - Montant - Longeron	Category is not precise, it will affect data visualization
 MOB_13 Meuble double écran Structure tubulaire galvanisé échafaudage : - Socle à vis - Montant - Longeron	Product was considered as concrete paver financial data might not be relevant
 MOB_13 Meuble double écran Structure tubulaire galvanisé échafaudage : - Socle à vis - Montant - Longeron	Purchase price is missing :it may affect the relevance of the financial data
 MOB_16 Table îlot cuisine Structure tubulaire galvanisé échafaudage : - Socle à vis - Montant - Longeron	Category is not precise, it will affect data visualization

ERROR REPORT (20 errors, 202 warnings)

Here are listed the errors and warnings that were generated during the calculation of the report. They are generally linked to insufficient or imprecise filling of product passports.

 - Warning: a data is missing - the concerned deposit has been taken into account but the result of the indicator for this deposit may be non representative or partial

 - Error: an important data is missing - the concerned deposit could not be taken into account in the calculation of the indicator

In both cases, we recommend that you modify or obtain the modification of the passports used, in order to obtain more accurate and qualitative reports.

	Deposit name	Error explanation
	MOB_16 Table îlot cuisine Structure tubulaire galvanisé échafaudage :- Socle à vis - Montant - Longeron	Product was considered as concrete paver financial data might not be relevant
	MOB_16 Table îlot cuisine Structure tubulaire galvanisé échafaudage :- Socle à vis - Montant - Longeron	Purchase price is missing :it may affect the relevance of the financial data
	MOB_02 Assise Gaines galvanisées carrées	Purchase price is missing :it may affect the relevance of the financial data
	MOB_03 Assise & Meuble expérience client Gaines galvanisées rectangulaires	Purchase price is missing :it may affect the relevance of the financial data
	MOB_03 Assise & Meuble expérience client Gaines galvanisées type coude S	Purchase price is missing :it may affect the relevance of the financial data
	MOB_19 Gradin Gaines S aluminium rivetées	Purchase price is missing :it may affect the relevance of the financial data
	TABOURETS EMPILABLES	Product was considered as concrete paver financial data might not be relevant
	TABOURETS EMPILABLES	Purchase price is missing :it may affect the relevance of the financial data
	FAUTEUIL	Purchase price is missing :it may affect the relevance of the financial data
	Rideau salle data - 6 ml à occulter	Purchase price is missing :it may affect the relevance of the financial data
	Rideau salle économie circulaire - 4,4 ml à occulter	Purchase price is missing :it may affect the relevance of the financial data
	Rideau salle nouveaux matériaux - 4,3 ml à occulter	Purchase price is missing :it may affect the relevance of the financial data
	Rideau salle nouveaux matériaux - 5,2 ml à occulter	Purchase price is missing :it may affect the relevance of the financial data
	Plateau de table L360 x P 120cm Plateau pierre ép.5cm issu du réemploi selon sourcing agenceur à valider choix architecte	Product was considered as concrete paver financial data might not be relevant
	Plateau de table L360 x P 120cm Plateau pierre ép.5cm issu du réemploi selon sourcing agenceur à valider choix architecte	Purchase price is missing :it may affect the relevance of the financial data

ERROR REPORT (20 errors, 202 warnings)

Here are listed the errors and warnings that were generated during the calculation of the report. They are generally linked to insufficient or imprecise filling of product passports.

 - Warning: a data is missing - the concerned deposit has been taken into account but the result of the indicator for this deposit may be non representative or partial

 - Error: an important data is missing - the concerned deposit could not be taken into account in the calculation of the indicator

In both cases, we recommend that you modify or obtain the modification of the passports used, in order to obtain more accurate and qualitative reports.

	Deposit name	Error explanation
	Plateaux de tables rectangulaire L210 x P 140cm Plateau pierre ép.5cm issu du réemploi selon sourcing agenceur	Product was considered as concrete paver financial data might not be relevant
	Plateaux de tables rectangulaire L210 x P 140cm Plateau pierre ép.5cm issu du réemploi selon sourcing agenceur	Purchase price is missing :it may affect the relevance of the financial data
	MOB_04 Meuble à tiroirs Tiroirs en plexiglas sur glissières	Purchase price is missing :it may affect the relevance of the financial data
	MOB_20 Barre de penderie salle "data" chemin de cable galvanisé pour la barre de penderie 12 cm largeur	Purchase price is missing :it may affect the relevance of the financial data
	MOB_20bis Etagère salle data L188 x P12cm Étagère chemin de câble vissé sur les tasseaux verticaux	Purchase price is missing :it may affect the relevance of the financial data
	MOB_01 Meuble Barre de penderie en acier galvanisé	Product was considered as concrete paver financial data might not be relevant
	MOB_01 Meuble Barre de penderie en acier galvanisé	Purchase price is missing :it may affect the relevance of the financial data
	MOB_09 Meuble écran et Pegboard : Panneau Pinboard	Category is not precise, it will affect data visualization
	MOB_09 Meuble écran et Pegboard : Panneau Pinboard	Purchase price is missing :it may affect the relevance of the financial data
	MOB_18 Compactus mobile config 01 Porte plaqué liège	Category is not precise, it will affect data visualization
	MOB_18 Compactus mobile config 01 Porte plaqué liège	Purchase price is missing :it may affect the relevance of the financial data
	MOB_16 Table îlot cuisine Plan en chute de marbre	Product was considered as concrete paver financial data might not be relevant
	MOB_16 Table îlot cuisine Plan en chute de marbre	Purchase price is missing :it may affect the relevance of the financial data
	MOB_13 Meuble double écran Mélaminé blanc pour caisson menuisé intérieur	Category is not precise, it will affect data visualization
	MOB_13 Meuble double écran Mélaminé blanc pour caisson menuisé intérieur	Purchase price is missing :it may affect the relevance of the financial data

ERROR REPORT (20 errors, 202 warnings)

Here are listed the errors and warnings that were generated during the calculation of the report. They are generally linked to insufficient or imprecise filling of product passports.

⚠ - Warning: a data is missing - the concerned deposit has been taken into account but the result of the indicator for this deposit may be non representative or partial

⊗ - Error: an important data is missing - the concerned deposit could not be taken into account in the calculation of the indicator

In both cases, we recommend that you modify or obtain the modification of the passports used, in order to obtain more accurate and qualitative reports.

	Deposit name	Error explanation
⚠	MOB_16 Table îlot cuisine Mélangé blanc pour caisson menuisé intérieur	Category is not precise, it will affect data visualization
⚠	MOB_16 Table îlot cuisine Mélangé blanc pour caisson menuisé intérieur	Purchase price is missing :it may affect the relevance of the financial data
⚠	MOB_17 Compactus mobile config 01 Armoire compactable à volant hors étagère et séparateurs verticaux	Purchase price is missing :it may affect the relevance of the financial data
⚠	MOB_18 Compactus mobile config 01 Armoire compactable à volant hors étagère et séparateurs verticaux	Purchase price is missing :it may affect the relevance of the financial data
⚠	Panneau textile compressé Cornière aluminium thermolaqué noir en tête de contre-cloison côté vitrage	Product was considered as concrete paver financial data might not be relevant
⚠	Panneau textile compressé Cornière aluminium thermolaqué noir en tête de contre-cloison côté vitrage	Purchase price is missing :it may affect the relevance of the financial data
⚠	Panneau végétal - Cornière aluminium thermolaqué noir en tête de contre-cloison	Purchase price is missing :it may affect the relevance of the financial data
⚠	Rideaux Thermiques - 31ml à occulter - 5 rideaux	Purchase price is missing :it may affect the relevance of the financial data
⚠	TABOURET	Product was considered as concrete paver financial data might not be relevant
⚠	TABOURET	Purchase price is missing :it may affect the relevance of the financial data
⚠	CLOISONS BA13	Purchase price is missing :it may affect the relevance of the financial data
⚠	CONTRE CLOISON PLACO autostable, renforts à prévoir pour la pose des meubles	Purchase price is missing :it may affect the relevance of the financial data

