



The circularity indicator is the result of an operation that takes into account both the previous lives of the materials integrated into products under consideration and the next possible usages for these deposits.

Please note that the figures given below are based on the information provided in the platform. Incorrect or missing information can lead to unrepresentative results for your deposits.



141 / 143 deposits considered
2,71 tons of deposits in total

PREVIOUS LIVES



NEXT USAGES

Disassemblability of products and deposits ●●●●○○

Identification and potential of future uses ●●●●●○

Presence and reliability of information ●●○○○○

	MOST PRESENT PRODUCT CATEGORY (IN MASS)	MOST CIRCULAR PRODUCT CATEGORY	LEAST CIRCULAR PRODUCT CATEGORY
Circularity grade	<p>58 / 100</p>	<p>94 / 100</p>	<p>7 / 100</p>
(1) % of recycled or rapidly renewable materials (2) % of deposits resulting from reuse	(1) (2)	(1) (2)	(1) (2)
Disassemblability of products and deposits	●●●●●○	●●●●●●	●●●●○○
Identification and potential of future uses	●●●●●○	●●●●●●	○○○○○○
Presence and reliability of information	●●○○○○	●●○○○○	●●●●●●
	INDOOR FURNITURE, ACCESSORIES & DÉCOR 1,40 tons 51,6% of the total weight	IT, AUDIOVISUAL & COMMUNICATION EQUIPMENT 0,070 tons 2,6% of the total weight	INTERIOR WALL COVERINGS 0,008 tons 0,3% of the total weight

ALL CATEGORIES

Category	Number of deposits considered	Weight (Tons)	% of total weight	Circularity grade	% of recycled or rapidly renewable materials	% of deposits resulting from reuse	Disassemblability of products and deposits	Identification and potential of future uses	Presence and reliability of information
Total	141	2,71	100,0%	59%	25%	0%	73%	86%	44%
IT, audiovisual & communication equipment	2	0,070	2,6%	93%	80%	0%	93%	100%	44%
Furniture and accessories	4	0,170	6,3%	87%	60%	0%	97%	100%	38%
Exterior joinery	1	0,000	0,0%	83%	50%	0%	93%	100%	40%
Sanitary systems / networks	5	0,029	1,1%	78%	53%	0%	67%	100%	69%
Facade	5	0,006	0,2%	77%	39%	0%	90%	92%	74%
Other construction products and materials	5	0,069	2,6%	66%	0%	0%	90%	99%	39%
Sanitary equipment	12	0,274	10,1%	62%	46%	0%	60%	89%	82%
Clothing	2	0,006	0,2%	60%	0%	0%	80%	100%	41%
Indoor furniture, accessories & décor	49	1,40	51,6%	57%	20%	0%	79%	83%	37%
Electrical installations – CFO/CFA networks	27	0,061	2,3%	52%	10%	0%	62%	82%	35%
Floor coverings	17	0,454	16,8%	51%	18%	0%	52%	81%	52%

ALL CATEGORIES

Category	Number of deposits considered	Weight (Tons)	% of total weight	Circularity grade	% of recycled or rapidly renewable materials	% of deposits resulting from reuse	Disassemblability of products and deposits	Identification and potential of future uses	Presence and reliability of information
Partitioning, wall lining & interior insulation	2	0,064	2,4%	51%	0%	0%	51%	96%	28%
Interior joinery	2	0,050	1,8%	50%	0%	0%	90%	100%	31%
Opening protections	4	0,045	1,7%	42%	0%	0%	48%	80%	22%
Other	2	0,004	0,1%	33%	100%	0%	60%	0%	14%
Interior wall coverings	2	0,008	0,3%	6%	15%	0%	60%	2%	100%

ERROR REPORT (2 errors, 52 warnings)

Here are listed the errors and warnings that were generated during the calculation of the report. They are generally linked to insufficient or imprecise filling of product passports.

 - Warning: a data is missing - the concerned deposit has been taken into account but the result of the indicator for this deposit may be non representative or partial

 - Error: an important data is missing - the concerned deposit could not be taken into account in the calculation of the indicator

In both cases, we recommend that you modify or obtain the modification of the passports used, in order to obtain more accurate and qualitative reports.

	Deposit name	Error explanation
	Prise	Conversion factor is missing and is necessary
	Prise	Conversion factor is missing and is necessary
	Tête de lit	Share of recycled material is not filled. It will be considered as null
	Interrupteur	Share of recycled material is not filled. It will be considered as null
	Prise	Share of recycled material is not filled. It will be considered as null
	Applique tête de lit	Share of recycled material is not filled. It will be considered as null
	Applique miroir	Share of recycled material is not filled. It will be considered as null
	Applique bureau	Share of recycled material is not filled. It will be considered as null
	Banquette	Share of recycled material is not filled. It will be considered as null
	Store d'occultation	Share of recycled material is not filled. It will be considered as null
	Spot bureau	Share of recycled material is not filled. It will be considered as null
	Dalle minérale	Share of recycled material is not filled. It will be considered as null
	miroir	Share of recycled material is not filled. It will be considered as null
	Poubelle	Share of recycled material is not filled. It will be considered as null
	spot	Share of recycled material is not filled. It will be considered as null

ERROR REPORT (2 errors, 52 warnings)

Here are listed the errors and warnings that were generated during the calculation of the report. They are generally linked to insufficient or imprecise filling of product passports.

 - Warning: a data is missing - the concerned deposit has been taken into account but the result of the indicator for this deposit may be non representative or partial

 - Error: an important data is missing - the concerned deposit could not be taken into account in the calculation of the indicator

In both cases, we recommend that you modify or obtain the modification of the passports used, in order to obtain more accurate and qualitative reports.

Deposit name	Error explanation
 Chaise	Share of recycled material is not filled. It will be considered as null
 Rideaux	Share of recycled material is not filled. It will be considered as null
 tête de lit	Category is not precise, it will affect data visualization
 Radiofrequency switch	Share of recycled material is not filled. It will be considered as null
 Piètement de Table	Category is not precise, it will affect data visualization
 Spot	Share of recycled material is not filled. It will be considered as null
 Applique mural	Share of recycled material is not filled. It will be considered as null
 WALL MIROIR SUSPENDED ON TV FUNCTION LINE	Share of recycled material is not filled. It will be considered as null
 Latte métal	Share of recycled material is not filled. It will be considered as null
 Spot	Share of recycled material is not filled. It will be considered as null
 Tête de lit	Share of recycled material is not filled. It will be considered as null
 Interrupteur	Share of recycled material is not filled. It will be considered as null
 Prise	Share of recycled material is not filled. It will be considered as null
 Applique tête de lit	Share of recycled material is not filled. It will be considered as null
 Applique miroir	Share of recycled material is not filled. It will be considered as null

ERROR REPORT (2 errors, 52 warnings)

Here are listed the errors and warnings that were generated during the calculation of the report. They are generally linked to insufficient or imprecise filling of product passports.

⚠ - Warning: a data is missing - the concerned deposit has been taken into account but the result of the indicator for this deposit may be non representative or partial

⊗ - Error: an important data is missing - the concerned deposit could not be taken into account in the calculation of the indicator

In both cases, we recommend that you modify or obtain the modification of the passports used, in order to obtain more accurate and qualitative reports.

Deposit name	Error explanation
⚠ Applique bureau	Share of recycled material is not filled. It will be considered as null
⚠ Banquette	Share of recycled material is not filled. It will be considered as null
⚠ Store d'occultation	Share of recycled material is not filled. It will be considered as null
⚠ Spot bureau	Share of recycled material is not filled. It will be considered as null
⚠ Chaise	Share of recycled material is not filled. It will be considered as null
⚠ Rideaux	Share of recycled material is not filled. It will be considered as null
⚠ tête de lit	Category is not precise, it will affect data visualization
⚠ Radiofrequency switch	Share of recycled material is not filled. It will be considered as null
⚠ Piètement de Table	Category is not precise, it will affect data visualization
⚠ Spot	Share of recycled material is not filled. It will be considered as null
⚠ Applique mural	Share of recycled material is not filled. It will be considered as null
⚠ WALL MIROIR SUSPENDED ON TV FUNCTION LINE	Share of recycled material is not filled. It will be considered as null
⚠ Chevets	Share of recycled material is not filled. It will be considered as null
⚠ Penderie	Share of recycled material is not filled. It will be considered as null
⚠ Chevets	Share of recycled material is not filled. It will be considered as null

ERROR REPORT (2 errors, 52 warnings)

Here are listed the errors and warnings that were generated during the calculation of the report. They are generally linked to insufficient or imprecise filling of product passports.

 - Warning: a data is missing - the concerned deposit has been taken into account but the result of the indicator for this deposit may be non representative or partial

 - Error: an important data is missing - the concerned deposit could not be taken into account in the calculation of the indicator

In both cases, we recommend that you modify or obtain the modification of the passports used, in order to obtain more accurate and qualitative reports.

	Deposit name	Error explanation
	Penderie	Share of recycled material is not filled. It will be considered as null
	Joue	Share of recycled material is not filled. It will be considered as null
	Bureau	Share of recycled material is not filled. It will be considered as null
	Joue	Share of recycled material is not filled. It will be considered as null
	Bureau	Share of recycled material is not filled. It will be considered as null
	Applique mural	Share of recycled material is not filled. It will be considered as null
	FAIENCE MURALE	Share of recycled material is not filled. It will be considered as null
	revêtement mural tête de lit	Category is not precise, it will affect data visualization
	revêtement mural tête de lit	Category is not precise, it will affect data visualization

